

PCN Number:	20160712000	PCN Date:	7/14/2016
Title:	Datasheet for TLV341, TLV341A, TLV342, TLV342S		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/> Assembly Site	<input type="checkbox"/> Design	<input type="checkbox"/> Wafer Bump Site	
<input type="checkbox"/> Assembly Process	<input checked="" type="checkbox"/> Data Sheet	<input type="checkbox"/> Wafer Bump Material	
<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Part number change	<input type="checkbox"/> Wafer Bump Process	
<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Site	<input type="checkbox"/> Wafer Fab Site	
<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Process	<input type="checkbox"/> Wafer Fab Materials	
		<input type="checkbox"/> Wafer Fab Process	

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification etc.

The product datasheet(s) is being updated as summarized below.

The following change history provides further details.



TLV341, TLV341A, TLV342, TLV342S
SLVS568D – JANUARY 2005 – REVISED APRIL 2016

Changes from Revision C (November 2007) to Revision D

Page

- Added ESD Ratings table, Feature Description section, Device Functional Modes, Application and Implementation section, Power Supply Recommendations section, Layout section, Device and Documentation Support section, and Mechanical, Packaging, and Orderable Information section 1
- Removed DPK package and TLV344 part from the Pin Configuration and Functions table 3

Device Family	Change From:	Change To:
TLV341	SLVS568C	SLVS568D

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TLV341>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

TLV341AIDBVR	TLV342AIDR	TLV341IDCKTG4	TLV342ID
TLV341AIDBVT	TLV341IDBVR	TLV341IDRLR	TLV342IDGKR
TLV341AIDBVTE4	TLV341IDBVRG4	TLV342AID	TLV342IDR
TLV341AIDCKR	TLV341IDCKR	TLV342AIDG4	TLV342IRUGR
TLV341AIDCKT	TLV341IDCKT	TLV342AIDRG4	TLV342SIRUGR
TLV341AIDCKTG4			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com