

## **TLE9261...63(-3)BQX(V33) Mid-Range+ SBC Family**

### **Reference: Data Sheet**

Infineon-TLE9263-3BQX-DS-v10\_00-EN, Rev 1.0

### **Errata Sheet**

---

### **Overview**

This document lists the errata of the Mid-Range+ SBC Family related to the Data Sheet:  
Infineon-TLE9263-3BQX-DS-v10\_00-EN, Rev 1.0.

It is strongly recommended that the device behavior and proposed workarounds are considered for the application.

#### **Affected products**

- TLE9261BQX,
- TLE9261-3BQX,
- TLE9261BQXV33,
- TLE9261-3BQXV33,
- TLE9262BQX,
- TLE9262-3BQX,
- TLE9262BQXV33,
- TLE9262-3BQXV33,
- TLE9263BQX,
- TLE9263-3BQX,
- TLE9263BQXV33,
- TLE9263-3BQXV33

**Unintended CAN dominant pulse when entering SBC Sleep or Fail-Safe Mode while**

## **1 Unintended CAN dominant pulse when entering SBC Sleep or Fail-Safe Mode while in CAN Normal Mode**

### **1.1 Description of behavior - occurrence**

**Necessary conditions:**

- CAN is in Normal mode with VCAN nominally supplied AND
  - SBC in Normal Mode OR
  - SBC in Stop Mode

**Unexpected device behavior:**

- For following SBC mode changes:
  - the device is sent to SBC Sleep Mode from SBC Normal Mode without changing the CAN mode OR
  - the device enters SBC Fail-Safe Mode
- If above conditions apply, then a typ. 2us dominant pulse is sent on the CANL and CANH and is also received on RXDCAN

*Note: the tolerance of the pulse is correlated with the oscillator frequency tolerance as specified in the datasheet parameter P\_15.10.25 ( $f_{CLKSBC}$ ).*

### **1.2 Possible impact**

This unexpected pulse could wake up other CAN nodes, which are not following the CAN wake-up pattern (WUP: dominant – recessive – dominant) according to ISO11898-6:2013 or ISO11898-2:2016

### **1.3 Root cause description**

In case the device is sent to SBC Sleep Mode or enters SBC Fail-Safe Mode while the CAN transceiver is in Normal mode, following device behavior applies:

- the I/O structures of the device are tied to LOW level at the same time the SBC Sleep Mode is entered
- however, the CAN transceiver stays in Normal mode (i.e. transmitter enabled) for another typ. 2us before it is automatically set to CAN wake capable mode.
- this LOW level of the I/Os is interpreted as a dominant level on the CANTXD pin until the CAN wake capable mode is entered (typ. 2us)

**Unintended CAN dominant pulse when entering SBC Sleep or Fail-Safe Mode while**

**1.4 Proposed workaround for SBC Sleep Mode**

Below mentioned workaround is only required if following conditions apply:

- The CAN wake-up pattern according to ISO11898-6:2013 or ISO 11898-2:2016 is not implemented on other ECUs, i.e. a single dominant pulse on the CAN bus could wake up the respective ECU
- SBC Sleep Mode is entered while CAN Normal Mode is configured, i.e. the described behavior is not present and the workaround is not required if SBC Stop Mode is selected or CAN is OFF, in CAN Receive Only mode or CAN wake capable mode

To avoid this behavior the SBC Sleep mode entry sequence should be adapted as follows:

- Before SBC Sleep Mode entry the CAN transceiver should be set to CAN wake capable mode, CAN Receive Only mode or CAN OFF
- Right after this command the device should then be set to SBC Sleep Mode

*Note: This workaround is backward compatible to the Mid Range SBC family but not required*

Other workarounds or combination of workarounds might also be possible and could be checked for the application.

**1.5 Corrective Action**

The datasheet update specifying to avoid CAN Normal mode when entering SBC Sleep Mode.

**Revision history**

## **2 Revision history**

<b>Revision</b>	<b>Date</b>	<b>Changes</b>
1.1	2019-01-18	Corrected title to match affected products.
1.0	2018-04-09	Initial release.

## Trademarks

All referenced product or service names and trademarks are the property of their respective owners.

**Edition 2019-01-18**

**Published by**

**Infineon Technologies AG**

**81726 Munich, Germany**

**© 2019 Infineon Technologies AG.**

**All Rights Reserved.**

**Do you have a question about any aspect of this document?**

**Email: [erratum@infineon.com](mailto:erratum@infineon.com)**

## IMPORTANT NOTICE

The information given in this document shall in no event be regarded as a guarantee of conditions or characteristics ("Beschaffenhheitsgarantie").

With respect to any examples, hints or any typical values stated herein and/or any information regarding the application of the product, Infineon Technologies hereby disclaims any and all warranties and liabilities of any kind, including without limitation warranties of non-infringement of intellectual property rights of any third party.

In addition, any information given in this document is subject to customer's compliance with its obligations stated in this document and any applicable legal requirements, norms and standards concerning customer's products and any use of the product of Infineon Technologies in customer's applications.

The data contained in this document is exclusively intended for technically trained staff. It is the responsibility of customer's technical departments to evaluate the suitability of the product for the intended application and the completeness of the product information given in this document with respect to such application.

For further information on technology, delivery terms and conditions and prices, please contact the nearest Infineon Technologies Office ([www.infineon.com](http://www.infineon.com)).

## WARNINGS

Due to technical requirements products may contain dangerous substances. For information on the types in question please contact your nearest Infineon Technologies office.

Except as otherwise explicitly approved by Infineon Technologies in a written document signed by authorized representatives of Infineon Technologies, Infineon Technologies' products may not be used in any applications where a failure of the product or any consequences of the use thereof can reasonably be expected to result in personal injury.