



**OVERVIEW**

|                             |   |                         |         |
|-----------------------------|---|-------------------------|---------|
| <b>DATE ISSUED:</b>         | 10/13/2021  | <b>TRACKING NUMBER:</b> | 4134874 |
| <b>ISSUED BY:</b>           | Sierra Wireless IIOT Solutions Product Management   |                         |         |
| <b>PRODUCTS AFFECTED:</b>   | HL7548, HL7588,HL7688, HL7648, HL7618RD, HL7650, HL7518, HL7690, HL7692   |                         |         |
| <b>SKUS AFFECTED:</b>       | HL7548: 1102411, 1102587, 1102732<br>HL7518: 1103261<br>HL7588: 1102498 1102561, 1103022, 1103051, 1103482, 1103554, 1103816, 1104001, 1104085<br>HL7618RD: 1103172<br>HL7648: 1103144, 1104084<br>HL7650: 1103218, 1103219, 1103946, 1103974<br>HL7688: 1103055, 1103334, 1103923<br>HL7690: 1103365<br>HL7692: 1103454, 1103717 |                         |         |
| <b>BULLETIN:</b>            | SKU EOL Notice: ASN Decoding issue in newly upgraded carrier network (Tracking #4134629, released back on September 15, 2018)   |                         |         |
| <b>URGENCY:</b>             | Urgent  |                         |         |
| <b>EFFECTIVE DATE:</b>      | Immediately   |                         |         |
| <b>FOR DISTRIBUTION TO:</b> | ALL HL75xx/HL76xx Customers   |                         |         |

**Summary**

The SKU EOL Notice is issued to notify customers of the HL75xx/HL76xx SKU's affected by *ASN Decoding issue in newly upgraded carrier network* being called End-of-Life.

**Details of Change**

Per previous Product bulletin HL75xx/HL76xx can potentially encounter an ASN.1 decoding issue, when carrier network is upgraded to higher 3GPP version. The solution with an Intel patch had been integrated and updated in all the latest SWI FW. Please refer to “*ASN Decoding issue in newly upgraded carrier network*” released in 2018 for more details.

The following ASN-issue affected SKU's will be called EOL.

| Affected SKU | Product Family | Replacment SKU         |
|--------------|----------------|------------------------|
| 1103261      | HL7518         | 1104100                |
| 1102411      | HL7548         | No Replacement         |
| 1102587      | HL7548         | 1104118, 1104253       |
| 1102732      | HL7548         | 1104128                |
| 1102498      | HL7588         | 1104117                |
| 1102561      | HL7588         | 1104081                |
| 1103022      | HL7588         | 1104117                |
| 1103051      | HL7588         | 1104439                |
| 1103482      | HL7588         | 1103030                |
| 1103554      | HL7588         | 1104081                |
| 1103816      | HL7588         | No Replacement         |
| 1104001      | HL7588         | 1104117                |
| 1104085      | HL7588         | No Replacement         |
| 1103172      | HL7618         | 1104077                |
| 1103144      | HL7648         | 1104116                |
| 1104084      | HL7648         | 1104145                |
| 1103218      | HL7650         | 1104146 (Telstra only) |
| 1103219      | HL7650         | 1104594 (Telstra only) |
| 1103946      | HL7650         | 1104488 (Telstra only) |
| 1103974      | HL7650         | 1104147                |
| 1103055      | HL7688         | 1104119, 1104285       |
| 1103334      | HL7688         | 1104119, 1104285       |
| 1103923      | HL7688         | 1104119, 1104285       |
| 1103365      | HL7690         | 1104191                |
| 1103454      | HL7692         | 1104070                |
| 1103717      | HL7692         | 1104070                |

## Effective Date

---

Targeted Date: Effective Immediately

## More information

---

For more information please contact your Sierra Wireless sales/technical support person.