

Product Change Notification

PCN #: 5C-2018

DATE: 10th May 2018

1 PRODUCTS AFFECTED

Laird Part Number	Description
BL652-SA-01	Bluetooth v5 Module + NFC (Integrated Antenna)
BL652-SC-01	Bluetooth v5 Module + NFC (External Antenna)
BL652-SA-01-T/R	Bluetooth v5 Module + NFC (Integrated Antenna) – Tape & Reel
BL652-SC-01-T/R	Bluetooth v5 Module + NFC (External Antenna) – Tape & Reel
DVK-BL652-SA-01	Development Kit - Bluetooth v5 Module + NFC (Integrated Antenna)
DVK-BL652-SC-01	Development Kit - Bluetooth v5 Module + NFC (External Antenna)

2 DESCRIPTION OF CHANGES

The BL652 Series of modules and associated development kits utilise the Nordic Semiconductor nRF52832-QFAA silicon. Starting from the **Build Code 1820** listed on each module's individual product label, Laird will be utilising the new E00 revision of the Nordic nRF52832-QFAA silicon inside the module.

There is no Form, Fit, Function, Quality or Reliability change in this PCN.

3 REASON FOR CHANGE

The BL652 Series of modules and associated development kits utilise the Nordic Semiconductor nRF52832-QFAA silicon. Nordic have recently announced via their 'Information Notice' programme (Notice no: IN-105, rev 1.0) that they are updating their Device version / Build Code from B00 to E00.

The Information Notice states the following:

Description of change:

New revision of the IC with the following key changes.

Fixes of anomalies

The new IC revision includes fixes for the following anomalies reported in nRF52832 Rev 1 Errata v1.6.

- #102 RADIO: PAYLOAD/END events delayed or not triggered after ADDRESS
- #106 RADIO: Higher CRC error rates for some access addresses
- #107 RADIO: Immediate address match for access addresses containing MSBs 0x00

nRF52832 Rev 2 will have its own Errata, nRF52832 Rev 2 Errata v1.0, which includes an updated list of anomalies.

In order to be drop-in compatible with current B00 / B10 build codes, the fix introduced is opt-in.

Impact: Does the change affect **product:**

- | | | |
|---------------------------|---|--|
| 1. Form | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes – describe: |
| 2. Fit | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes – describe: |
| 3. Function | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes – describe: |
| 4. Quality or Reliability | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes – describe: |
| Classification of change | <input checked="" type="checkbox"/> Minor | <input type="checkbox"/> Major |

Reason for change:

Fixed anomalies in affected devices.

Consequences of change:**Hardware**

The new device versions are drop-in compatible with the current versions.

Software:

The new device versions are software compatible with the current revision, but note the following:

- For the fix of anomalies to take effect, re-compilation with MDK version 8.15.1 and later is necessary
- It is also possible to manually enable the fix as described in nRF52832 Rev 2 Errata v1.0x, #182
- Note that SoftDevice S132 versions 4.0.2 until version 5.x have workarounds for the #102, #106 and #107 anomalies implemented.
- SoftDevice S132 version 6.x will apply the fix (according to Errata #182) for Rev2.

Teleregulatory and Bluetooth certification

- The new revision has no impact on RF performance
- The new revision inherits all Bluetooth QDIDs and requires no re-qualification for existing products

4 ANTICIPATED IMPACT OF THE CHANGE

- None

5 METHOD OF IDENTIFYING THE CHANGED PRODUCT

The change can be identified by reviewing the **Build Code** number that is present on the individual module, reel label and carton label. The images below identify where this **Build Code** is located on each of those labels.

A Build Code that starts with **1820**, and all subsequent incremental numbers, indicates that the nRF5283-QFAA-E00 silicon is utilised.

Label examples shown are for the -SA versions, all -SC versions follow the same format.

5.1 Module Label




Figure 1: Module label

5.2 Reel Label




Figure 2: Reel label

5.3 Carton Label




Figure 3: Master carton package label

6 FACTORY EFFECTIVITY DATE

This change has been implemented as a running change into Laird manufacturing of the BL652 Series modules. Production builds utilizing the new silicon revision will start from May 15th 2016 for BL652-SA parts and June 10th for BL652-SC parts. It is envisaged it will take some months for these modules to proliferate out into the global distribution channels.

7 CONTACT INFORMATION:

Headquarters	Laird 50 S Main St., Suite 1100 Akron, OH 44308 USA Tel: 1(330) 434-7929 Fax: 1(330) 434-7931
PCN Contact	pcn@lsr.com
Website	www.lairdtech.com
Technical Support	cs-support@lairdtech.com
Sales Contact	cs-sales@lairdtech.com

Product Change Notices (PCNs) will be distributed at the discretion of Laird. Occasionally, Laird may adjust product revision levels for internal tracking purposes only, and customers may not receive formal notifications associated with those revision changes.