

PRODUCT CHANGE NOTIFICATION

Product Category COPPER CONNECTORS 20221209-2

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 9-Dec-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Panduit is discontinuing various Copper Connectivity products without replacement. Please reference Part Numbers tab for affected part numbers.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2022	3	27

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Replacement Part 1
P110VCM300	NO-REPLACEMENT
P110VCM900	NO-REPLACEMENT
POEXPANEL-WH	NO-REPLACEMENT
CJQ688TGBL	NO-REPLACEMENT
CJQ6X88TGBL	NO-REPLACEMENT
CJSQ688TGBL	NO-REPLACEMENT
CJSQ6X88TGBL	NO-REPLACEMENT
VP24382TV25Y	NO-REPLACEMENT
TPA32R88S68Y	NO-REPLACEMENT
TPK2A32R88S68	NO-REPLACEMENT
AVPDB	NO-REPLACEMENT
NKMPT5E	NO-REPLACEMENT
SCHPDBVHDCI6/N	NO-REPLACEMENT