

## Product Advisory

Issue Date: September 21, 2020

**Change Type:**

New revision of Datasheet

**Parts Affected:**

BCM89230B1BCFBG  
BCM89230B2BCFBG  
BCM89230B1BCFBGT  
BCM89230B2BCFBGT  
BCM89231B1BPBG  
BCM89231B2BPBG  
BCM89231B1BPBGT  
BCM89231B2BPBGT

**Description and Extent of Change:**

- 8923X-DS109
  - Added B2 parts to Table 64, Ordering Information

**Reasons for Change:**

Additional versions of product added to the datasheet

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

Errata fixed in B2 version of the device. See Errata document 8953X-8923X-ES105 for details. If not affected by the errata you can stay with the B1 version of the product (no changes to B1 production support).

**Effective Date of Change:**

Datasheet 823X-DS109 was released on August 28, 2019

---

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.