

# Product Discontinuation

2010-09-02

OS-PD-2010-024

Last order:	August 31, 2011
Last delivery:	February 28, 2012

Reason: "Portfolio Reasons": Due to strategic reasons, the mentioned LEDs cannot be supported in the future anymore.

Please direct your inquiry to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
LSG T770				LSG T77K			
LSG T770-JL-1-0+JL-1-0-10-R18-Z	Q65110A2443	LED	MultiTOPLED RG	LSG T77K-JL-1-0+HK-1-0-2-R18-Z	Q65111A0238	LED	MultiTOPLED RG
LSG T770-K-1-0+L-1-0-10-R18-Z	Q65110A4966	LED	MultiTOPLED RG	LSG T77K-JL-1-0+HK-1-0-2-R18-Z	Q65111A0238	LED	MultiTOPLED RG
LSG T770-KL-1-0+KL-1-0-10-R18-Z-BP	Q65110A4620	LED	MultiTOPLED RG	LSG T77K-JL-1-0+HK-1-0-2-R18-Z	Q65111A0238	LED	MultiTOPLED RG

DISCONTINUED AND REPLACEMENT PARTS FOR OS-PD-2010-024					
DISCONTINUED			NEW (REPLACEMENT)		
Ordering Code	Part Number	Device	Ordering Code	Part Number	Device
		LSG T770			LSG T77K
Q65110A2443	LSG T770-JL+JL-1-Z	LSG T770-JL-1-0+JL-1-0-10-R18-Z	Q65111A0238	LSG T77K-JL-1-0+HK-1-0-2-Z	LSG T77K-JL-1-0+HK-1-0-2-R18-Z
Q65110A4966	LSG T770-K-1+L-1-Z	LSG T770-K-1-0+L-1-0-10-R18-Z	Q65111A0238	LSG T77K-JL-1-0+HK-1-0-2-Z	LSG T77K-JL-1-0+HK-1-0-2-R18-Z
Q65110A4620	LSG T770-KL-1-0+KL-1-Z-BP	LSG T770-KL-1-0+KL-1-0-10-R18-Z-BP	Q65111A0238	LSG T77K-JL-1-0+HK-1-0-2-Z	LSG T77K-JL-1-0+HK-1-0-2-R18-Z