

Product Advisory

Issue Date: July 1, 2021

Change Type:

ASIC component update only. No change to PCB layout or other BOM components.

Parts Affected:

BCM957508-P2100G
BCM957508-N2100G
BCM957504-P425G
BCM957504-N425G
BCM957504-N1100GD
BCM957504-M1100G16

Description and Extent of Change:

BCM5750X (Thor) ASIC stepping updated from B1 to B2, including Thor ASICs used on adapters.

Reasons for Change:

ASIC update routes SyncE network clock to an output pin and fixes multi-host issue. No impact to other functionality.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification will remain the same. No changes to adapter form, fit, function, quality and reliability.

Adapter revision number will increment.

Effective Date of Change:

The ASIC change will be implemented as a running change. Product shipments will begin after 12/31/2021.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.