

End Of Life Notice
(Notification – P2112054-DIG)
December 1, 2021

To: *Our Valued Digi-Key Electronics Customer*

Overview: The purpose of this notification is to communicate Renesas Electronics America, Inc. (REA) has begun the End of Life (EOL) Process on select Support Tools.

Affected Products: A review of our records indicates the list of products in the Appendix may affect your company.

Part numbers given in this list are for active part numbers in REA database at the time of this notification.

Key Dates:

Final last time buy (LTB) orders placed to REA or to a franchised REA distributor.	May. 15th, 2022
Planned date for last time shipment (LTS) from REA.	Aug. 15th, 2022

Response: Please place last time buy (LTB) orders in a timely manner prior to the key dates listed to avoid product availability issues. If you anticipate volumes beyond your regular rate, please contact your REA sales representative with a forecast of your requirements. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Any order resulting from this notice shall be governed by Renesas' General Terms and Conditions of Sale (<https://www.renesas.com/us/en/legal/terms-and-conditions.html>). Renesas will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please work with your REA sales representative and/or FAE to determine suitable replacement devices.

Please contact your REA sales representative for any questions or comments.

Thank you for your attention.

Sincerely,

Renesas Electronics America, Inc.

Appendix: Digi-Key Part List

Booking Part Number	Replacement PN	Supported Device; Repair Status
M3062PT3-CPE		M16C/62P; Repair available until the end of May 2025.
M30830T-EPB		M32C/83; Repair is not available.
M30850T3-CPE		M32/85; Repair available until the end of May 2025.
M30870T2-CPE		M32C/87; Repair available until the end of May 2025.
M30870T-EPB		M32C/87; Repair is not available.
M38D29T2-RLFS-FP		38D2; Repair is not available.
M38D59T-RLFS		38D5; Repair is not available.
QB-100GC-EA-09T	QB-100FB-EA-02T	78K0R/FX3; Repair is not available.
QB-100GF-HQ-01T	QB-100FA-HQ-01T	78K0/78K0R/V850; Repair is not available.
QB-100GF-NQ-01T	QB-100FA-NQ-01T	78K0/78K0R/V850; Repair is not available.
QB-100GF-YQ-01T	QB-100FA-YQ-01T	78K0/78K0R/V850; Repair is not available.
QB-128GF-HQ-01T	QB-128FB-HQ-01T	78K0/78K0R/V850; Repair is not available.
QB-128GF-NQ-01T	QB-128FB-NQ-01T	78K0/78K0R/V850; Repair is not available.
QB-128GF-YQ-01T	QB-128FB-YQ-01T	78K0/78K0R/V850; Repair is not available.
QB-208GD-YQ-01T	Available from TOKYO ELETECH CORPORATION (http://www.tetc.co.jp/e_enquete.htm)	Repair is not available.
QB-30MC-HQ-01T	QB-30SP-HQ-01T	78K0/78K0R/V850; Repair is not available.
QB-30MC-NQ-01T	QB-30SP-NQ-01T	78K0/78K0R/V850; Repair is not available.
QB-30MC-NQ-02T		78K0S/KX1; Repair is not available.
QB-30MC-YQ-01T	QB-30SP-YQ-01T	78K0/78K0R/V850; Repair is not available.
QB-50-EP-01T		78K0S/KX1; Repair is not available.
QB-52GB-HQ-01T	QB-52FA-HQ-01T	78K0/78K0R/V850; Repair is not available.
QB-52GB-NQ-01T	QB-52FA-NQ-01T	78K0/78K0R/V850; Repair is not available.
QB-52GB-YQ-01T	QB-52FA-YQ-01T	78K0/78K0R/V850; Repair is not available.
QB-64GA-HQ-01T		78K0R/KX3, 78K0R/IX3; Repair is not available.
QB-64GA-NQ-01T		78K0R/KX3, 78K0R/IX3, 78K0/KX2; Repair is not available.
ROC00000FDW12R	RTCZZZZZFD0AWNJ	Repair is not available.
ROC00000FDW13R	RTCZZZZZFD0AWNJ	Repair is not available.
ROC00000FDW13R#L5	RTCZZZZZFD0AWNJ#L5	Repair is not available.
ROC00000FDW13R#LA	RTCZZZZZFD0AWNJ#LA	Repair is not available.
ROC00000FDW13R#LT	RTCZZZZZFD0AWNJ#LT	Repair is not available.
ROE530640MCU00		M16C/64; Repair available until the end of May 2025.
ROK50100LS000BE	ROK50100LS900BE	RL78/G13; Repair is not available.
ROK50104PS000BE	ROK50104PS900BE	RL78/G14; Repair is not available.
ROK5010JGS000BE	ROK5010JGS900BE	RL78/G1C; Repair is not available.
ROK5010WMS000BE	ROK5010WMS900BE	RL78/L13; Repair is not available.
ROK505111S000BE	ROK505111S900BE	RX111; Repair is not available.
ROK505210S003BE	ROK505210S903BE	RX210; Repair is not available.
ROK505220S000BE	ROK505220S900BE	RX220; Repair is not available.
ROK505231S020BE		RX231; Repair is not available.
ROK505630S000BE		RX630; Repair is not available.
ROK50563TS000BE	ROK50563TS900BE	RX63T; Repair is not available.
ROK5562T0S000BE	ROK5562T0S900BE	RX62T; Repair is not available.
ROK5563THS000BE	ROK5563THS900BE	RX63T; Repair is not available.
ROK578G1CD010BR		RL78/G1C; Repair is not available.
ROK578L1CD000BR		RL78/L1C; Repair is not available.
ROK5RX231D000BR		RX231; Repair is not available.
RTK5RX2310P00000ZR		RX231; Repair is not available.
USCB17QS78K	ROC08500QSW01Nxx (xx=none,#L5,#LA,#LT) Compiler package V1 for V850 Family (w/IDE)	Repair is not available.
USCB17QS850	ROC07800QSW01Nxx (xx=none,#L5,#LA,#LT) Compiler package V1 for RL78,78K Family (w/IDE)	Repair is not available.