DIGI

Product Change Notification	Date June 30, 2022
Product	IX14/IX10/IX15/IX20/IX20W/IX30

Description of change	New firmware version 22.5.50.62 available for all IX routers. This is a major production release. Digi recommends all customers update their IX products to firmware v22.5.50.62

Reason for Change	New Firmware Version 22.5.50.62 provides: • New Features • Enhancements • Bug Fixes • Security Fixes See Release Notes for more details.

Product Notice	A new stable firmware version has been released for the IX, version 22.5.50.62. Use the link below to view the full list of changes, features, and fixes included in the new firmware. IX Release Notes **To take advantage of the new features, you must take action to update your device.** Refer to the instructions to update your firmware in the release notes above for more information. Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the Digi Support team *NOTE:* 22.5.50.62 will be the final major firmware release for the IX14 product. The end-of-life announcement for the IX14 occurred on 2021-07-21 (see PCN #210721-01)

Affected Part Numbers	IX14-L301, IX14-M301, IX14-M401, IX14-M601, IX14-M901, IX10-00G4, IX10-00N4, IX20-00M1, IX20-0AM1, IX20-W0M1, IX20-WAM1, IX20-00N4, IX20-0AN4, IX20-W0N4, IX20-WAN4, IX20-0007, IX20-W007, IX20-00G4, IX20-0AG4, IX20-W0G4, IX20-WAG4, IX15-00G4-XB2, IX15-00G4-XBP2, IX30-00P7, IX30-00G4, IX30-00A4

Timing of Change	Effective Immediately