Product Change Notification - SYST-18JZQK509

Date:

19 Oct 2018

Product Category:

Camera Flash LED Drivers

Affected CPNs:

📄 📊

Notification subject:

Data Sheet - MIC2870 - 1.5A Synchronous Boost Flash LED Driver with I2C Interface

Notification text:

SYST-18JZQK509

Microchip has released a new DeviceDoc for the MIC2870 - 1.5A Synchronous Boost Flash LED Driver with I2C Interface of devices. If you are using one of these devices please read the document located at MIC2870 - 1.5A Synchronous Boost Flash LED Driver with I2C Interface .

Notification Status: Final

Description of Change: 1) Converted Micrel document MIC2870 to Microchip data sheet DS20006078A. 2) Minor text changes throughout document.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 19 Oct 2018

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

MIC2870 - 1.5A Synchronous Boost Flash LED Driver with I2C Interface

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our PCN home page select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the PCN FAQ section.
If you wish to change your PCN profile, including opt out, please go to the PCN home page select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

SYST-18JZQK509 - Data Sheet - MIC2870 - 1.5A Synchronous Boost Flash LED Driver with I2C Interface

Affected Catalog Part Numbers(CPN)

MIC2870YFT-EV
MIC2870YFT-T5
MIC2870YFT-TR