

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Marking pattern update affecting TLE42694GM and TLE42794GM

N° 140/18

Marking pattern update affecting TLE42694GM and TLE42794GM

► **Products affected:** please refer to attached affected product list 1_cip14018

► **Detailed Change Information:**

Subject: The marking pattern of the products TLE42694GM and TLE42794GM build at Amkor Technologies, Philippines assembly site will be changed.

Reason: During transfer of TLE42694GM / TLE42794GM from Infineon Technologies (Malaysia) Sdn. Bhd., Melaka, Malaysia to Amkor Technologies, Philippines the marking pattern has been modified and will be set back to the same marking as the in-house variant before.

Description:	<u>Old</u>	<u>New</u>
Marking Pattern	<ul style="list-style-type: none">■ TLE42694GM: „42694G“■ TLE42794GM: „42794G“	<ul style="list-style-type: none">■ TLE42694GM: „42694GM“■ TLE42794GM: „42794GM“

► **Product Identification:** on marking pattern and package shape

► **Impact of Change:** no change of product itself; only change of marking

► **Attachments:** affected product list 1_cip14018

► **Intended start of delivery:** 25-April-2019

If you have any questions, please do not hesitate to contact your local Sales office.

Information note N° 140/18
Marking pattern update affecting TLE42694GM and TLE42794GM



Sales name	SP number	OPN	Package
TLE42694GM	SP001388588	TLE42694GMXUMA2	PG-DSO-14
TLE42794GM	SP001388590	TLE42794GMXUMA2	PG-DSO-14