



Micron Technology, Inc.  
8000 S. Federal Way  
PO Box 6  
Boise, ID United States

## End of Life Notification for B95A TLC NAND Flash Products

PCN: 31926

Published: 2016-05-03

### Revision History:

**Revision 1, 05/06/2016: This document supersedes the original PCN #31926, dated 2016-05-03. Last Purchase and Last Shipment dates have been changes to 2016-08-01 and 2016-08-31, respectively.**

<b>Type:</b>	End of Life
<b>Description:</b>	Micron is EOL'ing the B95A TLC NAND products.
<b>Reason:</b>	Change in Market Demand
<b>Product Affected:</b>	B95A NAND Flash

Affected Micron Part Number	Recommended Replacement	Customer Part Number
MT29F512G08EKCBBJ5-6:B	MT29F768G08EECBBJ4-37:B	
<u>Component</u>		
MT29F128G08EBCBBJ4-6:B	MT29F384G08EBCBBJ4-37:B	
MT29F128G08EBEBBB95A3WC1-M	N/A	
MT29F128G08EBEBBWP:B	MT29F384G08EBCBBJ4-37:B	
MT29F256G08EECBBJ4-6:B	MT29F384G08EBCBBJ4-37:B	
MT29F256G08EFEBBWP:B	MT29F384G08EBCBBJ4-37:B	
MT29F512G08EMCBBJ5-10:B	MT29F768G08EECBBJ4-37:B	
MT29F512G08EMCBBJ5-6:B	MT29F768G08EECBBJ4-37:B	

MT29F512G08EMCBBJ5-6:B.001

MT29F768G08EECBBJ4-37:B

Wafer

MT29F128G08EBEBBB95A3WC1

MT29F384G08EBHBBB0KB3WC1

\*Materials that have been ordered are in **bold**.

---

**Method of Identification:** Marketing Part Number

---

**Micron Sites Affected:** All Sites

---

**Last Purchase Date\*:** 2016-08-01

---

**Last Shipment Date:** 2016-08-31

\*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

**Micron Confidential and Proprietary Information**

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.