



End-Of-Life Notice

Product Group: Lamp product/ Mar.29.2012 / PCN-120329_Rev 1

The information included herein is property of LiteON. It shall not be revealed to unauthorized persons. For this mutual benefit of both partners, it's the policy of the company to inform customers of changes, which may concern LiteON products or their specifications.

Contact : George Lu, Product Marketing
Tel: 886-2-2226181 ext. 2392
E-mail: George.Lu@Liteon.com

Liteon Lamp End-Of-Life Announcement

Description:

LiteON-OPTO TH lamp products will discontinue the series part numbers and will be replaced by LiteON standard TH lamp solution as below table.

Products Affected:

As below table

Reason for Change:

Due to suppliers announced of stopping shipment original raw materials and operational constraints of the production line, we would like to End-Of-Life these products.

Last order/ Last Shipment

Last order acceptance to LiteON will be Jun-30, 2012

Last shipment form LiteON Thai-factory will be Sep-30, 2012

DS & Reliability evaluation data:

Available for all exist parts for replacement.

Sample Availability:

Available for all exist parts for replacement.

If there are no objections or requests for additional information by 04/15/12 received from our customers, then we assume approval for the proposed changes and can ship our product at the company discretion.

| Product | Alternatives |
|--------------------|---------------------------|
| LTL102SFK | LTL2F3VAKNT |
| LTL102SRHAP | - |
| LTL-16KE | LTL-1CHE |
| LTL-16KEE | LTL-1CHEE |
| LTL-16KG | LTL-1CHG |
| LTL-16KGE | LTL-1CHGE |
| LTL-16KPE-A | LTL-1CHE |
| LTL-1CHGEW-CA | LTL-1CHGE-0D1A |
| LTL1CHKGT | LTL1CHKGKNN |
| LTL1CHTBJ3 | LTL1CHTBJ3A or LTL1CHTBJ4 |
| LTL1CHTBK3 | LTL1CHTBK4 |
| LTL1CHVETS | LTL1CHJETNN |
| LTL1KHCBJ2 | LTL1KHCBP7T |
| LTL1KHCBJ2 | LTL1KHCBP7T |
| LTL1KHQGKP | LTL1KHKGKNN |
| LTL-1LHAE-002A | - |
| LTL-1NHGDK1 | LTL-1NHGP6 |
| LTL1RMTBK | LTL1RMTBK4-M |
| LTL1RMTGK | LTL42TG6N |
| LTL-1SMCK-SA4A | LTL1CHKRKNN |
| LTL-298DJ | - |
| LTL-298WJ | LTL-293SWJ |
| LTL2F3VAKNT | LTL2H3FX1K |
| LTL2F3VYKNT | LTL2H3PYK14 |
| LTL2G3VEK | LTL2H3EX1K |
| LTL2H3VAKNT | LTL2H3FX1K |
| LTL2H3VFKNT | LTL2H3FX1K |
| LTL2H3VRKNT | LTL2H3EX1K |
| LTL2H3VSKNT | LTL2H3PYK14 |
| LTL2H3VSKNT-072 | LTL2H3PYK14 |
| LTL2H3VYKNT | LTL2H3PYK14 |
| LTL2H3WFK-DL-032A | LTL2H3FX1K |
| LTL2K3QRKNNP | LTL2H3EX1K |



End-Of-Life Notice

Product Group: Lamp product/ Mar.29.2012 / PCN-120329_Rev 1

| | |
|--------------------|-------------------|
| LTL2P3EGK-002 | - |
| LTL2P3SEK | LTL2H3EX1K |
| LTL2P3SEK-002 | LTL2H3EX1K |
| LTL2P3SEK-M | LTL2H3EX1K |
| LTL2P3TBK4 | LTL2P3TBK5 |
| LTL2R36FTST-132A | LTL2R3KFKS-032A |
| LTL2R36FTST-132A | LTL2R3FW3K |
| LTL2R3UEJS-J | LTL2V3EU3KS |
| LTL2R3VFKNT | LTL2R3FW3K |
| LTL2R3VFKS-032A | LTL2R3FW3K |
| LTL2R3VRKNT | LTL2R3SVK2 |
| LTL2R3VSKNT | LTL2R3SVK2 |
| LTL2R3VYKNT | LTL2R3SVK2 |
| LTL2T3TBJ4LC | LTL2T3TBK5 |
| LTL2T3TBJ4-SA | LTL2T3TBK5 |
| LTL2T3TBK2 | LTL2T3TBK5 |
| LTL2T3TBK3 | LTL2T3TBK5 |
| LTL2T3TBK4 | LTL2T3TBK5 |
| LTL2T7TBK5 | LTL2T3TBK5 |
| LTL2V3SJ | LTL2R3SVK2 |
| LTL2V3UEK | LTL2V3VEKNT |
| LTL2V3USK | LTL2R3SVK2 |
| LTL2V3USK-002 | LTL2R3SVK2 |
| LTL-307CK | LTL2R3KRK |
| LTL-30EHK | LTL-30EHJ |
| LTL30EKLJ | - |
| LTL-30EWRJB-DA | LTL-30EHJ |
| LTL-3211A | LTL-433HR |
| LTL-3221A | LTL-433HR |
| LTL-3223A-001A | LTL-433HR |
| LTL-3223A-091A | LTL-433HR |
| LTL-3231A | LTL-433G |
| LTL-3233A | LTL-433G |
| LTL-3251A | LTL-433Y |



End-Of-Life Notice

Product Group: Lamp product/ Mar.29.2012 / PCN-120329_Rev 1

| | |
|--------------------|-------------------|
| LTL-334GDP1 | - |
| LTL353TGK | LTL2T3TGK6 |
| LTL-368FJ | LTL-293SJW |
| LTL-4221NLC-B | LTL-4221NLC |
| LTL-4232NPW | - |
| LTL-4266NUR | LTL-4266N |
| LTL42KE6N | LTL1CHKEKNN |
| LTL42QE2N | LTL1CHKEKNN |
| LTL4VMTBD3-002 | LTL3H3TBD4 |
| LTL-58EFJ | - |
| LTL5L3BRDS-002 | LTL5L3ES7D-E |
| LTL-643E | - |
| LTL-643G | - |
| LTL77HTBK | LTL87HTBK |
| LTL81HCBK2-132A | LTL87HTBK |
| LTW-102C4 | LTW-2R3D7 |
| LTW-102C4H6B | LTW-2R3D7 |
| LTW-1KHC5 | LTW-420DS4 |
| LTW-1THFC3J3 | LTW-4EMFDNJ2 |
| LTW-2E3C4 | LTW-2R3D7 |
| LTW-2H7C5S | LTW-2R3D7 |
| LTW-2L3C7S | LTW-2L3DV5S |
| LTW-2L3C7S-012A | LTW-2L3DV5S |
| LTW-2L3C7S-CO | LTW-2L3DV5S |
| LTW-2L3C7S-CO-012A | LTW-2L3DV5S |
| LTW-2N3C2 | LTW-2L3DV5S |
| LTW-2N3D7 | LTW-2L3DV5S |
| LTW-2N3D7-032 | LTW-2L3DV5S |
| LTW-2N3D7S | LTW-2L3DV5S |
| LTW-2N3D7S-032 | LTW-2L3DV5S |
| LTW-2R3D7LC | LTW-2R3D7 |
| LTW-2R3DX3 | LTW-2R3D7 |
| LTW-2R3T8 | LTW-2R3D7 |
| LTW-2S3D7-2 | LTW-2S3D7 |



End-Of-Life Notice

Product Group: Lamp product/ Mar.29.2012 / PCN-120329_Rev 1

| | |
|------------------|------------------|
| LTW-2S3D8-1-A | LTW-2S3D8 |
| LTW-2S3D8-1-A | LTW-2S3D8 |
| LTW-2S3DG1F | LTW-2S3D8 |
| LTW-2S3DG1F | LTW-2S3D8 |
| LTW-2S3T8 | LTW-2S3D8 |
| LTW-2V3C5 | LTW-2R3D7 |
| LTW-337C5 | LTW-2R3D7 |
| LTW-337C6 | LTW-2R3D7 |
| LTW-353D8 | LTW-2S3D7 |
| LTW-388D7 | LTW-2S3D6 |
| LTW-388D7P1 | LTW-2S3D6 |
| LTW-388D7P2 | LTW-2S3D6 |
| LTW-420D6 | LTW-420DS4 |
| LTW-487D3 | LTW-87HD4B |
| LTW-487D4B | LTW-87HD4B |
| LTW-487T8Y | LTW-87HD4B |
| LTW-487T8Y-B41A | LTW-87HD4B |
| LTW-488C2 | LTW-87HD4B |
| LTW-488D3 | LTW-87HD4B |
| LTW-4A3D4B | LTW-87HD4B |
| LTW-4DMD6J-1 | LTW-4DMD6J |
| LTW-77HC4 | LTW-87HD4B |
| LTW-815C4 | LTW-87HD4B |
| LTW-815D4 | LTW-87HD4B |
| LTW-815T4 | LTW-87HD4B |