



Product Change Notification - SYST-31MHIQ040

Date:

01 Sep 2018

Product Category:

General Purpose LED Drivers

Affected CPNs:



Notification subject:

Data Sheet - HV9803 LED Driver IC with Average-Mode Constant Current Control Data Sheet

Notification text:

SYST-31MHIQ040

Microchip has released a new DeviceDoc for the HV9803 LED Driver IC with Average-Mode Constant Current Control Data Sheet of devices. If you are using one of these devices please read the document located at [HV9803 LED Driver IC with Average-Mode Constant Current Control Data Sheet](#).

Notification Status: Final

Description of Change:

- 1) Converted Supertex Doc# DSFP-HV9803 to Microchip DS20005641A
- 2) Changed the packaging quantity for the 8-lead SOIC LG package from 2500/Reel to 3300/Reel
- 3) Added a maximum junction temperature to the Temperature Specifications Table
- 4) Made minor text changes throughout the document

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 01 Sep 2018

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[HV9803 LED Driver IC with Average-Mode Constant Current Control Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update



profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

HV9803BLG-G

HV9803BLG-G-S376

HV9803LG-G

HV9803LG-G-S374