

February 2nd, 2021

OBSOLETE NOTICE

This notice is to inform you that these two USB1.1 connectors, 1001-008-01001 and 1001-008**B**-0100, are obsolete.

For the USB 2.0 version, 1002-013-01001 is obsolete as well.

Thanks,

Hans
CnC Tech, LLC