

Issue Date: November 13th, 2019

Dear Valued Customer,

This notice is to inform you of changes affecting selected items that you have purchased from Littelfuse.

Description of the Change:

- Littelfuse will be re-sourcing stamped components, affecting the attached finished goods.

Reason for The Change:

- We have recently been notified that a legacy vendor will be immediately closing operations.
- To continue our supply of affected finished goods to you, we are seeking replacement components from existing vendors.

Effective Date of the Change:

- Littelfuse analysis of alternate components is ongoing. We are targeting to complete validation of all replacement components and finished goods before stock diminishes of existing components.

What You Need to Do:

- In response to this abrupt change, we have secured remaining stock of components and will soon confirm to you the changes necessary to sustain production, by finished good.
- Due to varying level of stock per component, and the number of finished goods they support, some finished goods will require component substitution sooner than others. In the subsequent pages, these part numbers and relative times of substitution are noted.

Any open orders will be handled on a customer-by-customer basis. For any questions, please feel free to reach out to either your Littelfuse Customer Service Representative or Inside Sales Representative.

We appreciate your continued partnership and business.

Sincerely,



Zachary Naughton
Global Product Manager
Littelfuse Commercial Vehicle Products

Current demand on the below finished goods will exhaust affected component inventory in Q1 2020. Replacement components are being identified currently and we will reach out to you soon regarding substitutions.

3029
3032
3051
6301
7785
12300
12301
31784
47052
50106
72092
72093
72095
72107
75719
91105
91126
95704
12300-BX
12301-BX
3029-BP
3029-BX
3029-WBXP
3032-BX
3051-BX
50086-02
50086-03
50086-04
5027-10

68166-07
68166-11
68166-14
68166-16
68166-19
68166-20
68369-02
72023-04
72086-02-WBXC
72092-WBXC
72106-01
75228-07
75228-07-BX
75228-14
75228-18
75228-22
75236-07
75237-01
75601-02
75601-06
75719-01
75906-01
7785-01
7785-01-BX
7785-02
7785-BX
7786-01
7786-03
7792-03

7803-01
7804-01
8735-01
90043-06
90043-07
90043-07-BX
90043-24
90043-25
90043-26
90043-31
90043-33
90043-35
90043-39
90043-44
90043-47
90071-02
90071-03
90073-04
90073-06
90073-07
9096-02
9096-02-BX
91045-07
91105-BX
91109-03
91113-05
91113-19
91113-20
91126-07

91126-BX
91812-02
91830-01
91830-03
92116-07
92126-01
95669-04
95690-03
95690-04
95690-05
95690-07
95690-09
95690-10
95690-10A
95704-01
95704-04
M-606
M-606-BP
M-606-BX
M-608
M-608-07
M-608-12
M-608-12-WBXV
M-608-BP
M-608-BX
M-91808

Current demand on the below finished goods will exhaust affected component inventory in summer of 2020. Replacement components are being identified currently and we will reach out to you Q1 2020 (at latest) regarding substitutions.

2506
7700
95614
2506-03
2506-13
2506-BX
30062-10
30062-15
30062-20
30062-20-BX
30062-30
30062-30-BX
30063-10
30063-20
30063-30
3261-01
7700-BX
90030-12
90030-15
90030-56
90060-06
90065-06
90065-07
90069-01
92107-14
9216-10
9224-26
95614-BX
M-626-10
PL-125-AC000

Current demand on the below finished goods will exhaust affected component inventory in Q3 2020. Replacement components are being identified currently and we will reach out to you summer 2020 (at latest) regarding substitutions.

47002
48122
48162
95037
48122-BX
48162-BX
72071-06-WBXC
90030-32
9270-01
9270-01-BX