

<b>PCN Number:</b>	20170911000A	<b>PCN Date:</b>	Dec 07, 2017
<b>Title:</b>	Carrier Tape Cavity Pitch Change for Select Devices		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Proposed 1<sup>st</sup> Ship Date:</b>	Mar 07, 2018		
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Assembly Process
<input type="checkbox"/>	Design	<input type="checkbox"/>	Electrical Specification
<input type="checkbox"/>	Test Site	<input checked="" type="checkbox"/>	Packing/Shipping/Labeling
<input type="checkbox"/>	Wafer Bump Site	<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>	Wafer Fab Site	<input type="checkbox"/>	Wafer Fab Materials
		<input type="checkbox"/>	Wafer Bump Process
		<input type="checkbox"/>	Wafer Fab Process
		<input type="checkbox"/>	Part number change

### PCN Details

#### Description of Change:

Revision A is to announce the **addition** of new devices that were not included on the original PCN notification. These new devices are highlighted and **bolded** in the device list below. The expected first shipment date for these new devices will be 90 days from this notice for these newly added devices only.

Texas Instruments is pleased to announce the qualification of a new carrier tape with a reduced cavity pitch.

What	From	To
Carrier Tape Pocket pitch	4mm	2mm
Drawing		

#### Reason for Change:

Standardization

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

None

#### Changes to product identification resulting from this PCN:

New Carrier tape

#### Product Affected:

LP5907UVX-1.8/NOPB	P5907UVX3.6-S	<b>LP5907UVE-4.5/NOPB</b>	<b>LP5907UVX1.875-S</b>
LP5907UVX-2.2/NOPB	P5907UVXXXXE	<b>LP5907UVX-1.2/NOPB</b>	<b>LP5907UVX19/NOPB</b>
LP5907UVX-2.75/NO	P5917A31YKER	<b>LP5907UVX-1.3/NOPB</b>	<b>LP5907UVX37/NOPB</b>
LP5907UVX1.825-S	<b>LP5907UVE-1.2/NOPB</b>	<b>LP5907UVX-2.5/NOPB</b>	<b>LP5908UVX1.75-S</b>
LP5908UVX128/Z	<b>LP5907UVE-1.8/NOPB</b>	<b>LP5907UVX-2.7/NOPB</b>	<b>LP5908UVX128/AZ</b>
LP5917A18YKER	<b>LP5907UVE-2.7/NOPB</b>	<b>LP5907UVX-2.8/NOPB</b>	<b>LP5917A30YKER</b>
P5907UVX1.6-S	<b>LP5907UVE-2.8/NOPB</b>	<b>LP5907UVX-3.0/NOPB</b>	<b>P5908UVX1.7-S</b>
LP5907UVX1.85-S	<b>LP5907UVE-3.0/NOPB</b>	<b>LP5907UVX-3.1/NOPB</b>	<b>P5908UVX1.75-S</b>
LP5907UVX2.925-S	<b>LP5907UVE-3.1/NOPB</b>	<b>LP5907UVX-3.2/NOPB</b>	<b>P5917A18YKER</b>

LP5908UVX-1.8/NOPB	<b>LP5907UVE-3.2/NOPB</b>	<b>LP5907UVX-3.3/NOPB</b>	<b>P5917A30YKER</b>
LP5908UVX128/J	<b>LP5907UVE-3.3/NOPB</b>	<b>LP5907UVX-4.5/NOPB</b>	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

<b>Location</b>	<b>E-Mail</b>
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>