



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631

[www.littelfuse.com](http://www.littelfuse.com)

---

To: Littelfuse Sales, Sales Support & Customers Valued Customer

From: Littelfuse Product Management – Industrial Business Unit

Subject: Obsolescence of LA Series, Semiconductor Fuses

Document Number: LFPCN\_PG0116

Date: 09/29/2020

This letter is to inform Littelfuse Sales, Sales Support & Customers of the obsolescence of 129-part numbers from our LA Series High Speed Semiconductor fuse offering, which are buy/resell Mersen branded fuses. Obsolescence is due to the availability of replacement Littelfuse brand PSR series fuses. This change will be effective immediately. Orders will be accepted for parts numbers that have inventory. Once inventory has been exhausted no new orders will be permitted. Please see page 2 for a complete listing of affected part numbers and their replacements. For any technical or cross reference questions, please contact our Technical Support team

Please update your ordering systems accordingly and thank you for your business.

Sincerely,  
**Augusto Sánchez**  
Product Manager

| Obsolete         | Replacement Part |  | Obsolete         | Replacement Part |  | Obsolete         | Replacement Part |
|------------------|------------------|--|------------------|------------------|--|------------------|------------------|
| LA060URD33LI2000 | PSR033UL2000X    |  | LA070URD31LI0315 | PSR031UL0315Z    |  | LA070URD33LI1000 | PSR033UL1000X    |
| LA065URD32LI1100 | PSR032UL1100X    |  | LA070URD31LI0350 | PSR031UL0350Z    |  | LA070URD33LI1100 | PSR033UL1100X    |
| LA065URD33LI1600 | PSR033UL1600X    |  | LA070URD31LI0400 | PSR031UL0400Z    |  | LA070URD33LI1250 | PSR033UL1250X    |
| LA065URD33LI1800 | PSR033UL1800X    |  | LA070URD31LI0450 | PSR031UL0450Z    |  | LA070URD33LI1400 | PSR033UL1400X    |
| LA070URD30KI0063 | PSR030US0063Z    |  | LA070URD31LI0500 | PSR031UL0500Z    |  | LA120URD72LI0630 | PSR072UL0630X    |
| LA070URD30KI0080 | PSR030US0080Z    |  | LA070URD31LI0550 | PSR031UL0550Z    |  | LA130URD70LI0063 | PSR070UL0063Z    |
| LA070URD30KI0100 | PSR030US0100Z    |  | LA070URD31LI0630 | PSR031UL0630Z    |  | LA130URD70LI0080 | PSR070UL0080Z    |
| LA070URD30KI0125 | PSR030US0125Z    |  | LA070URD31LI0700 | PSR031UL0700Z    |  | LA130URD70LI0100 | PSR070UL0100Z    |
| LA070URD30KI0160 | PSR030US0160Z    |  | LA070URD31LI0800 | PSR031UL0800Z    |  | LA130URD70LI0125 | PSR070UL0125Z    |
| LA070URD30KI0200 | PSR030US0200Z    |  | LA070URD32KI0400 | PSR032US0400X    |  | LA130URD70LI0160 | PSR070UL0160Z    |
| LA070URD30KI0250 | PSR030US0250Z    |  | LA070URD32KI0450 | PSR032US0450X    |  | LA130URD70LI0200 | PSR070UL0200Z    |
| LA070URD30KI0315 | PSR030US0315Z    |  | LA070URD32KI0500 | PSR032US0500X    |  | LA130URD70LI0250 | PSR070UL0250Z    |
| LA070URD30KI0350 | PSR030US0350Z    |  | LA070URD32KI0550 | PSR032US0550X    |  | LA130URD70LI0315 | PSR070UL0315Z    |
| LA070URD30KI0400 | PSR030US0400Z    |  | LA070URD32KI0630 | PSR032US0630X    |  | LA130URD71LI0160 | PSR071UL0160Z    |
| LA070URD30KI0450 | PSR030US0450Z    |  | LA070URD32KI0700 | PSR032US0700X    |  | LA130URD71LI0200 | PSR071UL0200Z    |
| LA070URD30KI0500 | PSR030US0500Z    |  | LA070URD32KI0800 | PSR032US0800X    |  | LA130URD71LI0250 | PSR071UL0250Z    |
| LA070URD30KI0550 | PSR030US0550Z    |  | LA070URD32KI0900 | PSR032US0900X    |  | LA130URD71LI0280 | PSR071UL0280Z    |
| LA070URD30LI0063 | PSR030UL0063Z    |  | LA070URD32KI1000 | PSR032US1000X    |  | LA130URD71LI0315 | PSR071UL0315Z    |
| LA070URD30LI0080 | PSR030UL0080Z    |  | LA070URD32LI0400 | PSR032UL0400X    |  | LA130URD71LI0350 | PSR071UL0350Z    |
| LA070URD30LI0100 | PSR030UL0100Z    |  | LA070URD32LI0450 | PSR032UL0450X    |  | LA130URD71LI0400 | PSR071UL0400Z    |
| LA070URD30LI0125 | PSR030UL0125Z    |  | LA070URD32LI0500 | PSR032UL0500X    |  | LA130URD71LI0450 | PSR071UL0450Z    |
| LA070URD30LI0160 | PSR030UL0160Z    |  | LA070URD32LI0550 | PSR032UL0550X    |  | LA130URD72LI0280 | PSR072UL0280X    |
| LA070URD30LI0200 | PSR030UL0200Z    |  | LA070URD32LI0630 | PSR032UL0630X    |  | LA130URD72LI0315 | PSR072UL0315X    |
| LA070URD30LI0250 | PSR030UL0250Z    |  | LA070URD32LI0700 | PSR032UL0700X    |  | LA130URD72LI0350 | PSR072UL0350X    |
| LA070URD30LI0315 | PSR030UL0315Z    |  | LA070URD32LI0800 | PSR032UL0800X    |  | LA130URD72LI0400 | PSR072UL0400X    |
| LA070URD30LI0350 | PSR030UL0350Z    |  | LA070URD32LI0900 | PSR032UL0900X    |  | LA130URD72LI0450 | PSR072UL0450X    |
| LA070URD30LI0400 | PSR030UL0400Z    |  | LA070URD32LI1000 | PSR032UL1000X    |  | LA130URD72LI0500 | PSR072UL0500X    |
| LA070URD30LI0450 | PSR030UL0450Z    |  | LA070URD33KI0500 | PSR033US0500X    |  | LA130URD72LI0550 | PSR072UL0550X    |
| LA070URD30LI0500 | PSR030UL0500Z    |  | LA070URD33KI0550 | PSR033US0550X    |  | LA130URD73LI0315 | PSR073UL0315X    |
| LA070URD30LI0550 | PSR030UL0550Z    |  | LA070URD33KI0630 | PSR033US0630X    |  | LA130URD73LI0350 | PSR073UL0350X    |
| LA070URD31KI0200 | PSR031US0200Z    |  | LA070URD33KI0700 | PSR033US0700X    |  | LA130URD73LI0400 | PSR073UL0400X    |
| LA070URD31KI0250 | PSR031US0250Z    |  | LA070URD33KI0800 | PSR033US0800X    |  | LA130URD73LI0450 | PSR073UL0450X    |
| LA070URD31KI0315 | PSR031US0315Z    |  | LA070URD33KI0900 | PSR033US0900X    |  | LA130URD73LI0500 | PSR073UL0500X    |
| LA070URD31KI0350 | PSR031US0350Z    |  | LA070URD33KI1000 | PSR033US1000X    |  | LA130URD73LI0550 | PSR073UL0550X    |
| LA070URD31KI0400 | PSR031US0400Z    |  | LA070URD33KI1100 | PSR033US1100X    |  | LA130URD73LI0630 | PSR073UL0630X    |
| LA070URD31KI0450 | PSR031US0450Z    |  | LA070URD33KI1250 | PSR033US1250X    |  | LA130URD73LI0700 | PSR073UL0700X    |
| LA070URD31KI0500 | PSR031US0500Z    |  | LA070URD33KI1400 | PSR033US1400X    |  | LA15QS202        | L15S020.T        |
| LA070URD31KI0550 | PSR031US0550Z    |  | LA070URD33LI0500 | PSR033UL0500X    |  | LA50QS101        | L50S010.T        |
| LA070URD31KI0630 | PSR031US0630Z    |  | LA070URD33LI0550 | PSR033UL0550X    |  | LA50QS121        | L50S012.T        |
| LA070URD31KI0700 | PSR031US0700Z    |  | LA070URD33LI0630 | PSR033UL0630X    |  | LA50QS151        | L50S015.T        |
| LA070URD31KI0800 | PSR031US0800Z    |  | LA070URD33LI0700 | PSR033UL0700X    |  | LA50QS201        | L50S020.T        |
| LA070URD31LI0200 | PSR031UL0200Z    |  | LA070URD33LI0800 | PSR033UL0800X    |  | LA50QS251        | L50S025.T        |
| LA070URD31LI0250 | PSR031UL0250Z    |  | LA070URD33LI0900 | PSR033UL0900X    |  | LA50QS301        | L50S030.T        |