



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Thursday 26th February, 2015

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that higher contact counts in the M22 series are being made obsolete. Typically, this involves pin counts over 20 pins per row – but this varies within each series. The following ranges are affected and have obsolete items within the range:

- M22-201xxxx
- M22-202xxxx
- M22-203xxxx
- M22-204xxxx
- M22-220xx46
- M22-221xx46
- M22-241xxxx
- M22-251xxxx
- M22-252xxxx
- M22-253xxxx
- M22-254xxxx
- M22-258xxxx
- M22-271xxxx
- M22-272xxxx
- M22-273xxxx
- M22-274xxxx
- M22-301xx00
- M22-302xx00
- M22-307xx00
- M22-533xx05
- M22-543xx05
- M22-552xxxx
- M22-552xxxxP
- M22-563xx05
- M22-634xx42
- M22-636xxxx
- M22-713xx42
- M22-714xx42

Unfortunately, we are no longer able to support these individual products. These items have been granted a 3 month Last Time Buy period – the products will **become obsolete on Monday 1st June 2015**. Please see the attached spreadsheet for a complete list of affected items, and suggested alternatives.

Please note we are not making the whole series obsolete.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

Obsolescence notification spreadsheet - M22 products Feb 2015

Series	Row	Existing Contacts per row	New Contacts per row	Obsolete
M22-201XXXX	SIL	From 02 to 50	From 02 to 25, 50	26 to 49
M22-202XXXX	DIL	From 02 to 50	From 02 to 25, 50	26 to 49
M22-203XXXX	SIL	From 02 to 50	From 02 to 25, 50	26 to 49
M22-204XXXX	DIL	From 02 to 50	From 02 to 25, 50	26 to 49
M22-220XX46	SIL	From 02 to 15	From 02 to 8	9 to 15
M22-221XX46	SIL	From 02 to 15	From 02 to 8	9 to 15
M22-241XXXX	DIL	From 03 to 40	From 03 to 25	26 to 40
M22-251XXXX	SIL	From 02 to 50	From 02 to 20, 25, 40, 50	21 to 24, 26 to 39, 41 to 49
M22-252XXXX	DIL	From 02 to 50	From 02 to 20, 25, 40	21 to 24, 26 to 39, 41 to 50
M22-253XXXX	SIL	From 02 to 50	From 02 to 20	21 to 50
M22-254XXXX	DIL	From 02 to 50	From 02 to 20	21 to 50
M22-258XXXX	DIL	From 02 to 50	From 02 to 15	16 to 50
M22-271XXXX	SIL	From 02 to 50	From 02 to 20	21 to 50
M22-272XXXX	DIL	From 02 to 50	From 02 to 20	21 to 50
M22-273XXXX	SIL	From 02 to 50	From 02 to 20	21 to 50
M22-274XXXX	DIL	From 02 to 50	From 02 to 20	21 to 50
M22-301XX00	SIL	From 02 to 30	From 02 to 20	21 to 30
M22-302XX00	DIL	From 02 to 40	From 02 to 20	21 to 40
M22-307XX00	SIL	From 02 to 15	From 02 to 10	11 to 15
M22-533XX05	SIL	From 02 to 40	From 02 to 15	16 to 40
M22-543XX05	DIL	From 03 to 25	From 03 to 15, 20	16 to 19, 21 to 25
M22-552XXXX	DIL	From 02 to 40	From 02 to 20	21 to 40
M22-552XXXXP	DIL	From 02 to 40	From 02 to 20	21 to 40
M22-563XX05	DIL	From 03 to 25	From 03 to 20	21 to 25
M22-634XX42	DIL	From 03 to 25	From 03 to 20	21 to 25
M22-636XXXX	DIL	From 02 to 32	From 02 to 20	21 to 32
M22-713XX42	SIL	From 03 to 32	From 03 to 20, 25	21 to 24, 26 to 32
M22-714XX42	DIL	From 03 to 32	From 03 to 25	26 to 32

See detail on sheet:

- Pin Headers (Variant)
- Pin Headers (Variant)
- Pin Headers (Variant)
- Pin Headers (Variant)
- Pin Headers (Other)
- Pin Headers (Other)
- Pin Headers (Other)
- Pin Headers (Variant)
- Pin Headers (Variant)
- Pin Headers (Variant)
- Pin Headers (Variant)
- Pin Headers (Variant)
- Pin Headers (Variant)
- Pin Headers (Variant)
- Pin Headers (Variant)
- Pin Headers (Variant)
- Sockets
- Sockets
- Sockets
- Pin Headers (Other)
- Pin Headers (Other)
- Pin Headers (Variant)
- Pin Headers (Variant)
- Pin Headers (Other)
- Sockets
- Sockets
- Sockets
- Sockets

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Nearest alternative product	Drawing for nearest alternative product	Pin Header Variant alternative product	Drawing for Pin Header Variant alternative product
M22-5522605	M22-552.pdf	M22-5521305	M22-552.pdf	M22-042000S2605	HF160-S.pdf
M22-5522646	M22-552.pdf	M22-5521346	M22-552.pdf	M22-042000S2646	HF160-S.pdf
M22-5522705	M22-552.pdf	M22-5521405	M22-552.pdf	M22-042000S2705	HF160-S.pdf
M22-5522746	M22-552.pdf	M22-5521446	M22-552.pdf	M22-042000S2746	HF160-S.pdf
M22-5522805	M22-552.pdf	M22-5521405	M22-552.pdf	M22-042000S2805	HF160-S.pdf
M22-5522846	M22-552.pdf	M22-5521446	M22-552.pdf	M22-042000S2846	HF160-S.pdf
M22-5522905	M22-552.pdf	M22-5521505	M22-552.pdf	M22-042000S2905	HF160-S.pdf
M22-5522946	M22-552.pdf	M22-5521546	M22-552.pdf	M22-042000S2946	HF160-S.pdf
M22-5523005	M22-552.pdf	M22-5521505	M22-552.pdf	M22-042000S3005	HF160-S.pdf
M22-5523046	M22-552.pdf	M22-5521546	M22-552.pdf	M22-042000S3046	HF160-S.pdf
M22-5523105	M22-552.pdf	M22-5521605	M22-552.pdf	M22-042000S3105	HF160-S.pdf
M22-5523146	M22-552.pdf	M22-5521646	M22-552.pdf	M22-042000S3146	HF160-S.pdf
M22-5523205	M22-552.pdf	M22-5521605	M22-552.pdf	M22-042000S3205	HF160-S.pdf
M22-5523246	M22-552.pdf	M22-5521646	M22-552.pdf	M22-042000S3246	HF160-S.pdf
M22-5523305	M22-552.pdf	M22-5521705	M22-552.pdf	M22-042000S3305	HF160-S.pdf
M22-5523346	M22-552.pdf	M22-5521746	M22-552.pdf	M22-042000S3346	HF160-S.pdf
M22-5523405	M22-552.pdf	M22-5521705	M22-552.pdf	M22-042000S3405	HF160-S.pdf
M22-5523446	M22-552.pdf	M22-5521746	M22-552.pdf	M22-042000S3446	HF160-S.pdf
M22-5523505	M22-552.pdf	M22-5521805	M22-552.pdf	M22-042000S3505	HF160-S.pdf
M22-5523546	M22-552.pdf	M22-5521846	M22-552.pdf	M22-042000S3546	HF160-S.pdf
M22-5523605	M22-552.pdf	M22-5521805	M22-552.pdf	M22-042000S3605	HF160-S.pdf
M22-5523646	M22-552.pdf	M22-5521846	M22-552.pdf	M22-042000S3646	HF160-S.pdf
M22-5523705	M22-552.pdf	M22-5521905	M22-552.pdf	M22-042000S3705	HF160-S.pdf
M22-5523746	M22-552.pdf	M22-5521946	M22-552.pdf	M22-042000S3746	HF160-S.pdf
M22-5523805	M22-552.pdf	M22-5521905	M22-552.pdf	M22-042000S3805	HF160-S.pdf
M22-5523846	M22-552.pdf	M22-5521946	M22-552.pdf	M22-042000S3846	HF160-S.pdf
M22-5523905	M22-552.pdf	M22-5522005	M22-552.pdf	M22-042000S3905	HF160-S.pdf
M22-5523946	M22-552.pdf	M22-5522046	M22-552.pdf	M22-042000S3946	HF160-S.pdf
M22-5524005	M22-552.pdf	M22-5522005	M22-552.pdf	M22-042000S4005	HF160-S.pdf
M22-5524046	M22-552.pdf	M22-5522046	M22-552.pdf	M22-042000S4046	HF160-S.pdf
M22-5522105P	M22-552P.pdf	M22-5322105	M22-532.pdf	M22-042000S2105	HF160-S.pdf
M22-5522146P	M22-552P.pdf	M22-5322146	M22-532.pdf	M22-042000S2146	HF160-S.pdf
M22-5522205P	M22-552P.pdf	M22-5322205	M22-532.pdf	M22-042000S2205	HF160-S.pdf
M22-5522246P	M22-552P.pdf	M22-5322246	M22-532.pdf	M22-042000S2246	HF160-S.pdf
M22-5522305P	M22-552P.pdf	M22-5322305	M22-532.pdf	M22-042000S2305	HF160-S.pdf
M22-5522346P	M22-552P.pdf	M22-5322346	M22-532.pdf	M22-042000S2346	HF160-S.pdf
M22-5522405P	M22-552P.pdf	M22-5322405	M22-532.pdf	M22-042000S2405	HF160-S.pdf
M22-5522446P	M22-552P.pdf	M22-5322446	M22-532.pdf	M22-042000S2446	HF160-S.pdf
M22-5522505P	M22-552P.pdf	M22-5322505	M22-532.pdf	M22-042000S2505	HF160-S.pdf
M22-5522546P	M22-552P.pdf	M22-5322546	M22-532.pdf	M22-042000S2546	HF160-S.pdf
M22-5522605P	M22-552P.pdf	M22-5521305	M22-552.pdf	M22-042000S2605	HF160-S.pdf
M22-5522646P	M22-552P.pdf	M22-5521346	M22-552.pdf	M22-042000S2646	HF160-S.pdf
M22-5522705P	M22-552P.pdf	M22-5521405	M22-552.pdf	M22-042000S2705	HF160-S.pdf
M22-5522746P	M22-552P.pdf	M22-5521446	M22-552.pdf	M22-042000S2746	HF160-S.pdf
M22-5522805P	M22-552P.pdf	M22-5521405	M22-552.pdf	M22-042000S2805	HF160-S.pdf
M22-5522846P	M22-552P.pdf	M22-5521446	M22-552.pdf	M22-042000S2846	HF160-S.pdf
M22-5522905P	M22-552P.pdf	M22-5521505	M22-552.pdf	M22-042000S2905	HF160-S.pdf
M22-5522946P	M22-552P.pdf	M22-5521546	M22-552.pdf	M22-042000S2946	HF160-S.pdf
M22-5523005P	M22-552P.pdf	M22-5521505	M22-552.pdf	M22-042000S3005	HF160-S.pdf
M22-5523046P	M22-552P.pdf	M22-5521546	M22-552.pdf	M22-042000S3046	HF160-S.pdf
M22-5523105P	M22-552P.pdf	M22-5521605	M22-552.pdf	M22-042000S3105	HF160-S.pdf
M22-5523146P	M22-552P.pdf	M22-5521646	M22-552.pdf	M22-042000S3146	HF160-S.pdf
M22-5523205P	M22-552P.pdf	M22-5521605	M22-552.pdf	M22-042000S3205	HF160-S.pdf
M22-5523246P	M22-552P.pdf	M22-5521646	M22-552.pdf	M22-042000S3246	HF160-S.pdf
M22-5523305P	M22-552P.pdf	M22-5521705	M22-552.pdf	M22-042000S3305	HF160-S.pdf
M22-5523346P	M22-552P.pdf	M22-5521746	M22-552.pdf	M22-042000S3346	HF160-S.pdf
M22-5523405P	M22-552P.pdf	M22-5521705	M22-552.pdf	M22-042000S3405	HF160-S.pdf
M22-5523446P	M22-552P.pdf	M22-5521746	M22-552.pdf	M22-042000S3446	HF160-S.pdf
M22-5523505P	M22-552P.pdf	M22-5521805	M22-552.pdf	M22-042000S3505	HF160-S.pdf
M22-5523546P	M22-552P.pdf	M22-5521846	M22-552.pdf	M22-042000S3546	HF160-S.pdf
M22-5523605P	M22-552P.pdf	M22-5521805	M22-552.pdf	M22-042000S3605	HF160-S.pdf
M22-5523646P	M22-552P.pdf	M22-5521846	M22-552.pdf	M22-042000S3646	HF160-S.pdf
M22-5523705P	M22-552P.pdf	M22-5521905	M22-552.pdf	M22-042000S3705	HF160-S.pdf
M22-5523746P	M22-552P.pdf	M22-5521946	M22-552.pdf	M22-042000S3746	HF160-S.pdf
M22-5523805P	M22-552P.pdf	M22-5521905	M22-552.pdf	M22-042000S3805	HF160-S.pdf
M22-5523846P	M22-552P.pdf	M22-5521946	M22-552.pdf	M22-042000S3846	HF160-S.pdf
M22-5523905P	M22-552P.pdf	M22-5522005	M22-552.pdf	M22-042000S3905	HF160-S.pdf
M22-5523946P	M22-552P.pdf	M22-5522046	M22-552.pdf	M22-042000S3946	HF160-S.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Nearest alternative product	Drawing for nearest alternative product	Pin Header Variant alternative product	Drawing for Pin Header Variant alternative product
M22-5524005P	M22-552P.pdf	M22-5522005	M22-552.pdf	M22-042000S4005	HF160-S.pdf
M22-5524046P	M22-552P.pdf	M22-5522046	M22-552.pdf	M22-042000S4046	HF160-S.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Nearest alternative product	Drawing for nearest alternative product	Other alternative product	Drawing for other alternative product
M22-2200946	M22-220.pdf	M22-2010946	M22-201.pdf		
M22-2201046	M22-220.pdf	M22-2011046	M22-201.pdf		
M22-2201146	M22-220.pdf	M22-2011146	M22-201.pdf		
M22-2201246	M22-220.pdf	M22-2011246	M22-201.pdf		
M22-2201346	M22-220.pdf	M22-2011346	M22-201.pdf		
M22-2201446	M22-220.pdf	M22-2011446	M22-201.pdf		
M22-2201546	M22-220.pdf	M22-2011546	M22-201.pdf		
M22-2210946	M22-221.pdf	M22-2030946	M22-203.pdf		
M22-2211046	M22-221.pdf	M22-2031046	M22-203.pdf		
M22-2211146	M22-221.pdf	M22-2031146	M22-203.pdf		
M22-2211246	M22-221.pdf	M22-2031246	M22-203.pdf		
M22-2211346	M22-221.pdf	M22-2031346	M22-203.pdf		
M22-2211446	M22-221.pdf	M22-2031446	M22-203.pdf		
M22-2211546	M22-221.pdf	M22-2031546	M22-203.pdf		
M22-2412642	M22-241.pdf	M22-2411342	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2412646	M22-241.pdf	M22-2411346	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2412742	M22-241.pdf	M22-2411442	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2412746	M22-241.pdf	M22-2411446	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2412842	M22-241.pdf	M22-2411442	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2412846	M22-241.pdf	M22-2411446	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2412942	M22-241.pdf	M22-2411542	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2412946	M22-241.pdf	M22-2411546	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2413042	M22-241.pdf	M22-2411542	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2413046	M22-241.pdf	M22-2411546	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2413142	M22-241.pdf	M22-2411642	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2413146	M22-241.pdf	M22-2411646	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2413242	M22-241.pdf	M22-2411642	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2413246	M22-241.pdf	M22-2411646	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2413342	M22-241.pdf	M22-2411742	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2413346	M22-241.pdf	M22-2411746	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2413442	M22-241.pdf	M22-2411742	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2413446	M22-241.pdf	M22-2411746	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2413542	M22-241.pdf	M22-2411842	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2413546	M22-241.pdf	M22-2411846	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2413642	M22-241.pdf	M22-2411842	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2413646	M22-241.pdf	M22-2411846	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2413742	M22-241.pdf	M22-2411942	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2413746	M22-241.pdf	M22-2411946	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2413842	M22-241.pdf	M22-2411942	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2413846	M22-241.pdf	M22-2411946	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2413942	M22-241.pdf	M22-2412042	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2413946	M22-241.pdf	M22-2412046	M22-241.pdf	M22-2045046	M22-204.pdf
M22-2414042	M22-241.pdf	M22-2412042	M22-241.pdf	M22-2045005	M22-204.pdf
M22-2414046	M22-241.pdf	M22-2412046	M22-241.pdf	M22-2045046	M22-204.pdf
M22-5331605	M22-533.pdf	M22-5330805	M22-533.pdf		
M22-5331705	M22-533.pdf	M22-5330905	M22-533.pdf		
M22-5331805	M22-533.pdf	M22-5330905	M22-533.pdf		
M22-5331905	M22-533.pdf	M22-5331005	M22-533.pdf		
M22-5332005	M22-533.pdf	M22-5331005	M22-533.pdf		
M22-5332105	M22-533.pdf	M22-5331105	M22-533.pdf		
M22-5332205	M22-533.pdf	M22-5331105	M22-533.pdf		
M22-5332305	M22-533.pdf	M22-5331205	M22-533.pdf		
M22-5332405	M22-533.pdf	M22-5331205	M22-533.pdf		
M22-5332505	M22-533.pdf	M22-5331305	M22-533.pdf		
M22-5332605	M22-533.pdf	M22-5331305	M22-533.pdf		
M22-5332705	M22-533.pdf	M22-5331405	M22-533.pdf		
M22-5332805	M22-533.pdf	M22-5331405	M22-533.pdf		
M22-5332905	M22-533.pdf	M22-5331505	M22-533.pdf		
M22-5333005	M22-533.pdf	M22-5331505	M22-533.pdf		
M22-5333105	M22-533.pdf	M22-5331105	M22-533.pdf		
M22-5333205	M22-533.pdf	M22-5331105	M22-533.pdf		
M22-5333305	M22-533.pdf	M22-5331105	M22-533.pdf		
M22-5333405	M22-533.pdf	M22-5331205	M22-533.pdf		

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Nearest alternative product	Drawing for nearest alternative product	Other alternative product	Drawing for other alternative product
M22-5333505	M22-533.pdf	M22-5331205	M22-533.pdf		
M22-5333605	M22-533.pdf	M22-5331205	M22-533.pdf		
M22-5333705	M22-533.pdf	M22-5331305	M22-533.pdf		
M22-5333805	M22-533.pdf	M22-5331305	M22-533.pdf		
M22-5333905	M22-533.pdf	M22-5331305	M22-533.pdf		
M22-5334005	M22-533.pdf	M22-5331405	M22-533.pdf		
M22-5431605	M22-543.pdf	M22-5430805	M22-543.pdf	M22-5631605	M22-563.pdf
M22-5431705	M22-543.pdf	M22-5430905	M22-543.pdf	M22-5631705	M22-563.pdf
M22-5431805	M22-543.pdf	M22-5430905	M22-543.pdf	M22-5631805	M22-563.pdf
M22-5431905	M22-543.pdf	M22-5431005	M22-543.pdf	M22-5631905	M22-563.pdf
M22-5432105	M22-543.pdf	M22-5431105	M22-543.pdf		
M22-5432205	M22-543.pdf	M22-5431105	M22-543.pdf		
M22-5432305	M22-543.pdf	M22-5431205	M22-543.pdf		
M22-5432405	M22-543.pdf	M22-5431205	M22-543.pdf		
M22-5432505	M22-543.pdf	M22-5431305	M22-543.pdf		
M22-5632105	M22-563.pdf	M22-5631105	M22-563.pdf		
M22-5632205	M22-563.pdf	M22-5631105	M22-563.pdf		
M22-5632305	M22-563.pdf	M22-5631205	M22-563.pdf		
M22-5632405	M22-563.pdf	M22-5631205	M22-563.pdf		
M22-5632505	M22-563.pdf	M22-5631305	M22-563.pdf		