



Microsemi Corporation

Date Issued: March 12, 2014

Product Discontinuance Notification (PDN) No: 009-5

Description: CCFL Inverters & LED Driver Modules (Power Supplies) for LED Lighting Fixtures (Limited Parts List, see page 3)

Reason for Discontinuance: No/Low Demand. Microsemi's subcontractors are no longer supporting this product.

Customer Impact: None

Replacement Parts: None are recommended

Last Order Date: Contact factory immediately for LTB. Note that availability will be handled on a case by case and as needed basis.

Last Shipment Date: Any order agreed to will be required to be shipped ASAP, and would be Non Cancellable, Non Refundable

Products Affected by this Discontinuance: See list below on page 3

Contact Information:

James Howell
Director of Quality & Reliability
Tel. # (011) 714-372-8090
Email: jhowell@microsemi.com

Microsemi Corporation
One Enterprise, Aliso Viejo CA 92656 USA
Within the USA: +1 (949) 380-6100 · Sales: +1 (949) 380-6136
Fax: +1 (949) 215-4996 · www.microsemi.com

ICG-F-0004

Discontinuance Notice



Regards,

Microsemi Corporation

Any projected dates in this notification are based on the most current product information at the time this PDN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Microsemi Sales Office, the factory contact shown above, or your local distributor.

This PDN is confidential and proprietary information of Microsemi and is intended only for distribution by Microsemi to its customers, for customers' use only. It must not be copied or provided to any third party without Microsemi's prior written consent.

Products Affected by PDN 009-5

Discontinuance Notice

Product	Product	Product
LXM1597-01	LXM1598-01	LXM1612-05-01
LXM1612-05-02	LXM1612-05-03	LXM1612-12-03
LXM1615-03-04	LXM1617-05-41	LXM1617-05-43
LXM1618-12-42	LXM1621-02	LXM1622-12-01
LXM1623-12-41	LXM1643-12-62	LXM1643-12-63
LXMG1618-03-21	LXMG1618-03-22	
LXMG1612-05-01	LXMG1612-05-02	LXMG1614E-14-30051
LXMG1614E-14-30063	LXMG1615-03-01	LXMG1615-03-02
LXMG1617-03-21	LXMG1617-03-22	LXMG1617-05-21
LXMG1617-05-41	LXMG1617-05-62	LXMG1617A-03-21
LXMG1617A-12-42	LXMG1618-05-42	LXMG1618-05-61
LXMG1618-05-62	LXMG1618-12-41	LXMG1618A-03-21
LXMG1618A-03-22	LXMG1618A-05-21	LXMG1618A-05-41
LXMG1618A-12-62	LXMG1621-03	LXMG1622-12-01
LXMG1623-05-42	LXMG1623-05-62	LXMG1623-12-42
LXMG1624-12-42	LXMG1627-05-61	LXMG1627-12-42
LXMG1644-12-61	LXMG1800_LS	LXMG1811-05-61
LXMG1811-05-61S	LXMG1811-05-62	LXMG1811-05-62S
LXMG1813-12-62	LXMG1813-12-62S	LXMG1930-28-03
LXMG1930-28-04	LXMG1960-28-03	LXMG221D-0700040-D2F
LXMG221W-0350017-D0	LXMG221W-0700030-D0	LXMG221W-0700034-D0
LXMG221W-0700034-D1	LXMG222W-0350034-D0	
LXMG1611-01	LXMG1612-12-01	LXMG1612-12-02
LXMG1617A-03-22	LXMG1617A-05-21	LXMG1617A-05-22
LXMG1617A-05-62	LXMG1617A-12-62	LXMG1618-12-61
LXMG1618-12-62	LXMG1618A-05-22	LXMG1618A-05-61
LXMG1618A-12-42	LXMG1623-05-44	LXMG1626-05-66
LXMG1626-05-67	LXMG1627-05-42	LXMG1628-12-62
LXMG1813-12-61	LXMG1813-12-61S	LXMG1930-28-01