



# Product Change Notification

## TE Connectivity

Product Change Notification: P-21-020906

PCN Date: 11-MAY-21

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
Hermetic Connectors

**Description of Changes**  
Manufacturing location change. Adding Incertec, with address: Edificio 13A-D Parque Industrial Bella Vista, Carretera Internacional KM.1969 Guadalajara - Nogales KM.2, Empalme, Sonora, Mexico, 85340, as an additional plating source for the following Hermetic connectors listed.  
**Other attachments:**  
[Cross Reference13](#)

**Reason for Changes:**  
Dear Customer, as a result of our continuous strive for improving our processes and lead times, we hereby inform you about the addition of a new plating supplier for Hermetic connectors. Validation of this new supplier is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	05-JUL-2021
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DIV41H11-05PA</a>	NO						
<a href="#">DIV41H11-05PB</a>	NO						
<a href="#">DIV41H11-05PC</a>	NO						
<a href="#">DIV41H11-05PN</a>	NO						
<a href="#">DIV44H11-35PN</a>	NO						
<a href="#">DIV44H17-26PN</a>	NO						
<a href="#">DIV44H21-35PN</a>	NO						
<a href="#">DIV44H25-35PN</a>	NO						
<a href="#">DIV46H13-98SN-4041</a>	NO						
<a href="#">DJL11H8-35PN-034</a>	NO						
<a href="#">DJT11H09-35PN-034</a>	NO						
<a href="#">DJT11H11-35PA</a>	NO						
<a href="#">DJT11H11-35PN</a>	NO						
<a href="#">DJT11H13-35PN</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DJT14H11-35PN</a>	NO						
<a href="#">DJT14H13-35PN-034</a>	NO						
<a href="#">DJT14H15-35PN</a>	NO						
<a href="#">DJT14H15-97PN-034</a>	NO						
<a href="#">DJT14H25-35PN</a>	NO						
<a href="#">YDIV41H11-05PNV003</a>	NO			DIV41H11-05PN[V003], <b>DIV41H11-05PN [V003]</b>			
<a href="#">YDJT11H09-35PNC157</a>	NO			DJT11H09-35PN-034[V003], <b>DJT11H09-35PN-034 [V003]</b>			
<a href="#">YDJT11H11-35PAV003</a>	NO			DJT11H11-35PA[V003], <b>DJT11H11-35PA [V003]</b>			
<a href="#">YDJT11H11-35PNV003</a>	NO			DJT11H11-35PN[V003], <b>DJT11H11-35PN [V003]</b>			