

Date: 05/26/2017

**PRODUCT CHANGE NOTIFICATION #10039**

**Notification of:** .100" contact center Male Header Part Number discontinued with replacement.

**Date Change Effective:** May 23, 2017

**Explanation of change (from, to):**

DISCONTINUED	REPLACED WITH	DRAWING #
L_C__S__N-M30 A_C__S__N(-M30, -M508) Y_C__S__N-M30	G_C__S__N-M596 RMC__S__N(-M30, -M508) QMC__S__N-M30	C10058
L_C__D__N-M30 A_C__D__N(-M30, -M508) Y_C__D__N-M30	G_C__D__N-M596 RMC__D__N(-M30, -M508) QMC__D__N-M30	C10059
L_C__S__N-M89 A_C__S__N(-M89, -M511) Y_C__S__N-M89	G_C__S__N-M308 RMC__S__N(-M89, -M511) QMC__S__N-M89	C10060
L_C__D__N A_C__D__N(OMIT, -M500) Y_C__D__N	G_C__D__N-M594 RMC__D__N(OMIT, -M500) QMC__D__N	C10419
L_C__S__N A_C__S__N(OMIT, -M500) Y_C__S__N	G_C__S__N-M594 RMC__S__N(OMIT, -M500) QMC__S__N	C10436
L_C__S__N A_C__S__N(OMIT, -M500) Y_C__S__N	G_C__S__N-M594 RMC__S__N(OMIT, -M500) QMC__S__N	C10909
L_C__D__N A_C__D__N(OMIT, -M500) Y_C__D__N	G_C__D__N-M594 RMC__D__N(OMIT, -M500) QMC__D__N	C10912
L_C__D__N-M71 A_C__D__N(-M71, -M509) Y_C__D__N-M71	G_C__D__N-M595 RMC__D__N(-M71, -M509) QMC__D__N-M71	C11028
L_C__SAAR A_C__SAAR(OMIT, -M500) Y_C__SAAR	G_C__SAAR-M594 RMC__SAAR(OMIT, -M500) QMC__SAAR	C11110
L_C__S__N-M71 A_C__S__N(-M71, -M509) Y_C__S__N-M71	G_C__S__N-M595 RMC__S__N(-M71 -M509) QMC__S__N-M71	C11432
L_C__S__N-M105 A_C__S__N-M105 Y_C__S__N-M105	G_C__S__N-M597 RMC__S__N-M105 QMC__S__N-M105	C12721



**Reason for change:**

- (1) Contact Material Beryllium Copper used in discontinued part number (Material code 'A' & 'Y') is replaced with Phosphor Bronze.
- (2) For consistency, part number coding 'L' replaced with 'G' without specification change.

**Anticipated impact on fit, form, or function (positive/negative):** Positive

**Parts/Products affected:** .100" contact centers, male breakaway headers

**Parts prior to change will remain active for purchase?**

Yes \_\_\_ No X

**New or revised parts are interchangeable to the previous part applications?**

Yes X No \_\_\_

**Engineering Approval:**

Truong Tran

05.26.17

\_\_\_\_\_  
(Signature)

\_\_\_\_\_  
(Printed Name)

\_\_\_\_\_  
(Date)

Distribution: Website, Distributors, Customers, Internal

Information regarding this change notification and other previously issued change notifications can be found on our website: [www.sullinscorp.com/techcenter](http://www.sullinscorp.com/techcenter). If you have any questions or concerns, please contact us at [Support@sullinscorp.com](mailto:Support@sullinscorp.com) or call us at (760) 744-0125.

Sincerely,

**Sullins Connector Solutions**