



Product Change Notification

TE Connectivity

Product Change Notification: P-18-016044

PCN Date: 05-JUL-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing Location Change of Menlo Park Appliances Tubing FL2500 size 2,3 &4 Products to Trutnov

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from Menlo Park USA to Trutnov CZ. This notification is to inform our customers that TE Connectivity is closing our Menlo Park facility in USA and moving the production to our Trutnov facility in Czech Republic. The receiving facility in Trutnov is already an established Heat Shrinkable Tubing manufacturing site.

Other attachments:

[PCN FL2500 sizes 2,3, & 4](#)

[PCN FL2500 Packaging details](#)

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. As part of the production move, we will start to ship FL2500 products sizes 2,3 &4 from 4th October 2018 from the Trutnov facility. After this date TE reserves the right to provide qualified products from either the Menlo Park or Trutnov manufacturing locations during this transfer until the final closure date of Menlo Park location by the end of 2019. As not all part numbers will transfer at the same time customers may still receive Products from the Menlo Park location after this transfer date due to inventory we will carry to allow this transfer to happen and to minimize impact to our tubing customers.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 04-OCT-2018 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | 04-JUL-2019 |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|--|------------------------|---------------------------------|---------------------------|
| 363884-000 | NO | | | "1-1199654-7", "FL2500-NO.3-J1-0-STK" | | | |
| 771113P006 | NO | | | "4-1196007-3", "FL2500-NO.2-I9-0-65MM" | | | |
| E43149-000 | NO | | | "3-1199653-6", "FL2500-NO.2-I9-0-STK" | | | |
| E95757-000 | NO | | | "4-1199653-3", "FL2500-NO.4-J2-0-STK" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|--|------------------------|---------------------------------|---------------------------|
| 363884-000 | NO | | | "1-1199654-7", "FL2500-NO.3-J1-0-STK" | | | |
| 771113P006 | NO | | | "4-1196007-3", "FL2500-NO.2-I9-0-65MM" | | | |
| E95757-000 | NO | | | "4-1199653-3", "FL2500-NO.4-J2-0-STK" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|--|------------------------|---------------------------------|---------------------------|
| 771113P006 | NO | | | "4-1196007-3", "FL2500-NO.2-I9-0-65MM" | | | |
| E95757-000 | NO | | | "4-1199653-3", "FL2500-NO.4-J2-0-STK" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---------------------------------------|------------------------|---------------------------------|---------------------------|
| E43149-000 | NO | | | "3-1199653-6", "FL2500-NO.2-I9-0-STK" | | | |
| E95757-000 | NO | | | "4-1199653-3", "FL2500-NO.4-J2-0-STK" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---------------------------------------|------------------------|---------------------------------|---------------------------|
| E43149-000 | NO | | | "3-1199653-6", "FL2500-NO.2-I9-0-STK" | | | |
| E95757-000 | NO | | | "4-1199653-3", "FL2500-NO.4-J2-0-STK" | | | |