


Thursday 17th March, 2022

Dear Customer,


Re: Product Change Notification for Harwin product.

Please be advised that the solder cup on the M80-PF5 high power female contact has been deepened. This will also affect all Datamate Mix-Tek or Datamate Power connector assemblies that includes the contact number PF5. The solder cup change can be seen in this comparison – our solder testing has shown no effect on fit, form or function:

Old Design:



New Design:



Existing stock will be to the old design. The new design has now started production and will replace the old design as stocks are exhausted. The Technical Drawings and CAD Models for the contact are updated on the website. CAD Models for assemblies will be adjusted soon, and Technical drawings for assemblies will be adjusted at the time of future updates. Please contact us if you need any assembly models or drawings adjusted.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team

technical@harwin.com