



Expertise Applied | Answers Delivered

8755 W. Higgins Road

Suite 500

Chicago, IL 60631

www.littelfuse.com

LF PCN# A0116 Puller ATO/Mini 165.0005.000x

March 15, 2017

Dear Valued Customer,

Littelfuse is changing the color of the ATO/Mini fuse **Puller 165.0005.0002 and 165.0005.0001** from black to yellow. Littelfuse is making this change due to difficulties experienced by customers that have designed the puller into their fuse boxes: their quality scanners can not 'see' the black puller inside the black box. By changing the color to yellow, the puller becomes more visible both to the human eye, as well as in electronic scanner systems.

There is no change to the puller other than the colorant used in the resin. The yellow colorant added to the current resin has been fully tested in the harsh under-the-hood environment, and has been in use with other Littelfuse pullers for many years.

Littelfuse is in the process of implementing this change immediately, but the change will be implemented as a running change so customers may continue to receive stock in the black color as we work through our safety stock of the black variation.

Please contact your local Littelfuse representative if you have any additional questions. We will be pleased to answer any questions you may have. Thank you for your continued support.

Best Regards,

Jenny Kiolbasa

Jenny Kiolbasa

Littelfuse Automotive Business Unit

Passenger Car Products

jkiolbasa@littelfuse.com