

NO: CON-069	PRODUCT: XG4A and XG4M – Flat Ribbon Cable Connector
DATE: December 2015	TYPE: Modification – 1) Marking Method, XG4A / XG4M 2) Remove Ridges, XG4A

XG4A and XG4M Flat Ribbon Cable Connectors Marking Method Changes and Ridges Removed from Surface of XG4A

In an effort to standardize the factory’s production methods and improve productivity, various models of the **XG4A and XG4M Flat Ribbon Cable Connectors** will experience a change to the marking method of the connectors. Additionally, a portion of the XG4A’s surface will have ridges removed from the face of the connector. The following details will illustrate the physical changes; should you have any additional questions, however, please communicate with the Connector Product Specialist.

There will be no impact on technical specifications or price as a result of these changes.







Effective Date

As of our production in **July, 2016**.

* Please, advise your customers of this notification.
For further technical support and any questions, please communicate with Omron Electronic Components LLC.

Details of the Changes

Before the change	After the change
<p>Marking Method (XG4A and XG4M) Thermal Transfer</p> 	<p>Laser Marking</p> 
<p>Shape (XG4A, only) Ridges present</p> 	<p>Smooth surface</p> 

Details of Applicable Models

Model Number	Model Number	Model Number	Model Number	Model Number
XG4A-1031	XG4A-2034	XG4A-3435-8	XG4A-6035	XG4M-2030
XG4A-1031-8	XG4A-2034-3	XG4A-3436	XG4A-6036	XG4M-2030-T
XG4A-1032	XG4A-2034-8	XG4A-3439-A	XG4A-6039-A	XG4M-2030-U
XG4A-1033	XG4A-2035	XG4A-4031	XG4A-6071	XG4M-2630
XG4A-1034	XG4A-2036	XG4A-4031-8	XG4A-6071-D	XG4M-2630-T
XG4A-1034-3	XG4A-2039-A	XG4A-4032	XG4A-6072	XG4M-2630-U
XG4A-1034-8	XG4A-2431	XG4A-4033	XG4A-6073	XG4M-3030
XG4A-1035	XG4A-2631	XG4A-4034	XG4A-6074	XG4M-3030-T
XG4A-1036	XG4A-2631-3	XG4A-4034-8	XG4A-6075	XG4M-3030-U
XG4A-1039-A	XG4A-2632	XG4A-4035	XG4A-6076	XG4M-3430
XG4A-1071	XG4A-2632-8	XG4A-4036	XG4A-6079-A	XG4M-3430-T
XG4A-1072	XG4A-2633	XG4A-4039-A	XG4A-6431	XG4M-3430-U
XG4A-1073	XG4A-2634	XG4A-5031	XG4A-6432	XG4M-4030
XG4A-1074	XG4A-2634-3	XG4A-5031-8	XG4A-6433	XG4M-4030-T
XG4A-1075	XG4A-2634-8	XG4A-5032	XG4A-6434	XG4M-4030-U
XG4A-1076	XG4A-2635	XG4A-5033	XG4A-6435	XG4M-4031-T
XG4A-1079-A	XG4A-2635-8	XG4A-5034	XG4A-6436	XG4M-4031-U
XG4A-1431	XG4A-2636	XG4A-5034-8	XG4A-6439-A	XG4M-5030
XG4A-1432	XG4A-2639-A	XG4A-5035	XG4A-6471	XG4M-5030-T
XG4A-1433	XG4A-3031	XG4A-5036	XG4A-6472	XG4M-5030-U
XG4A-1434	XG4A-3031-8	XG4A-5039	XG4A-6473	XG4M-5031
XG4A-1435	XG4A-3032	XG4A-5039-A	XG4A-6474	XG4M-5031-T
XG4A-1436	XG4A-3033	XG4A-5071	XG4A-6475	XG4M-5031-U
XG4A-1439-A	XG4A-3034	XG4A-5071-8	XG4A-6476	XG4M-6030
XG4A-1631	XG4A-3034-8	XG4A-5071-D	XG4A-6479-A	XG4M-6030-T
XG4A-1631-8	XG4A-3035	XG4A-5072	XG4A-64A	XG4M-6030-U
XG4A-1632	XG4A-3036	XG4A-5073	XG4M-1030	XG4M-6031
XG4A-1633	XG4A-3039	XG4A-5074	XG4M-1030-T	XG4M-6031-T
XG4A-1634	XG4A-3039-A	XG4A-5074-8	XG4M-1030-U	XG4M-6031-U
XG4A-1634-8	XG4A-3431	XG4A-5075	XG4M-1031	XG4M-6430
XG4A-1635	XG4A-3431-8	XG4A-5076	XG4M-1031-T	XG4M-6430-T
XG4A-1636	XG4A-3431-D	XG4A-5079-A	XG4M-1031-U	XG4M-6430-U
XG4A-1639-A	XG4A-3432	XG4A-6031	XG4M-1430	XG4M-6431
XG4A-2031	XG4A-3432-8	XG4A-6031-8	XG4M-1430-T	XG4M-6431-T
XG4A-2031-3	XG4A-3433	XG4A-6032	XG4M-1430-U	XG4M-6431-U
XG4A-2031-8	XG4A-3434	XG4A-6033	XG4M-1630	
XG4A-2032	XG4A-3434-8	XG4A-6034	XG4M-1630-T	
XG4A-2033	XG4A-3435	XG4A-6034-8	XG4M-1630-U	

* Please, advise your customers of this notification.

For further technical support and any questions, please communicate with Omron Electronic Components LLC.

Specifications in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.