

# PRODUCT CHANGE NOTIFICATION

PCN#: ID, SAFETY AND ACCESSORIES **20190213-1**

ISSUE DATE: 20190218

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Not Required for discontinuation)**

GMY2-W material thickness is changing from 1.5mil to 1.0mil due to supplier product change.

Photos/Drawing (where applicable)

**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2019	4	1
Old product discontinuation date*	2019	4	1

**\*Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
PEL-10-Y2-5	
PEL-11-Y2-5	
PEL-12-Y2-2.5	
PEL-13-Y2-2.5	
PEL-14-Y2-1	
PEL-16-Y2-0.5	
PEL-1-Y2-10	
PEL-29-Y2-10	
PEL-2-Y2-10	
PEL-3-Y2-5	
PEL-4-Y2-10	
PEL-5-Y2-10	
PEL-6-Y2-5	
PEL-7-Y2-5	
PEL-A4-Y2-25	
PLL-20-Y2-10	
PLL-24-Y2-1	
PLL-24-Y2-5	
PLL-2-Y2-10	
PLL-32-Y2-10	
PLL-4-Y2-10	
PLL-5-Y2-10	