

### 1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type			
01	001	025	0000000207	See list below	Protection	UST 1206







\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected				
3413.0331.11	3413.0331.22	3413.0331.24	3413.0331.26	
3413.0332.11	3413.0332.22	3413.0332.24	3413.0332.26	

### 2 Type of change

Change of terminal layout

### 3 Detailed description of change

Old product appearance (example)	New product appearance (example)
<p>Top side:  Bottom side: </p> <p></p>	<p>Top side:  Bottom side: </p> <p></p> <p>Might have steps in:</p> <ul style="list-style-type: none"> <li>• the pad corners of the top side</li> <li>• the whole pad of the bottom side</li> </ul>

### 4 Reason of change

Change of terminal layout for improved burr reduction handling

### 5 Release date

The change takes effect in ww 22/2018 (Date code 1822 or higher on label).

### 6 Impact of change and recommended action

Form	Yes	Change of terminal section appearance
Fit	No	No change for dimension
Function	No	No change in function, datasheet specification remain as before.
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

### 7 Reference Documents / Attachments

Kind of document	Remarks
<a href="#">Data Sheet</a>	

Product Change Notification					UST 1206 20A/25A Terminal improvement		
owner	creation date	release date	released by	change order no	rev	page	
ganderka	06.04.2018	13.04.2018	haeckima	2015154	B	1 of 1	D10-018-391