



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000975I

DATE: 16-Aug-2019

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX16073RS17D3+	N/A			Part reactivated from prior notice: M000940I
Reactivation	MAX16073RS17D3+T	N/A			Part reactivated from prior notice: M000940I
Lead-Free Conversion	MAX4253EBC	MAX4253EBC+T	14-Nov-2019	14-Nov-2019	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX6695AUB	MAX6695AUB+	14-Nov-2019	14-Nov-2019	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS4426T+T&R	N/A	14-Nov-2019	14-Nov-2019	Part can no longer be manufactured
Discontinuance	ICL7660C/D	N/A	14-Nov-2019	14-Nov-2019	Part can no longer be manufactured
Discontinuance	ICL7660M/D	N/A	14-Nov-2019	14-Nov-2019	Part can no longer be manufactured
Discontinuance	ICL7662C/D	N/A	14-Nov-2019	14-Nov-2019	Part can no longer be manufactured
Discontinuance	ICL7664AC/D	N/A	14-Nov-2019	14-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX1771C/D	N/A	14-Nov-2019	14-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX40016-2LABS#	MAX40016LABS-2#	14-Nov-2019	14-Nov-2019	EVKIT is No Longer Supported
Discontinuance	MAX40026ATAY+	N/A	16-Aug-2019	16-Aug-2019	The part was not released
Discontinuance	MAX40026ATAY+T	N/A	16-Aug-2019	16-Aug-2019	The part was not released
Discontinuance	MAX44284HAWT+CKM	MAX44284HAWT+T	14-Nov-2019	14-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX6769TALD2/VY+T	N/A	14-Nov-2019	14-Nov-2019	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 16-Sep-2019