

500988  
PCN Number

3/23/2016  
Creation Date

## Change Management Worksheet

**Initiator** Mary Ma

**Product Family** DVI items

**RPM Number** NA

**ECN # / QN # / PCN #** 500988/C2016-5324

**Initiating Location Plant #** 1701 & 1702

**Initiating Location plant Name** Molex DongGuan

**Change Description**  
This letter is to inform you that The parts on the attached file will be obsolete without replacement due to aging toolings for DVI connector and local suppliers also obsoleted or plan to obsolete DVI connector because of low demand from market.

**Reason for short notice exception** Not Applicable

**Reason for Change** 5. Obsolete

**Plant Date of Implementation** 5/23/2017

**Photos**

--	--

--	--

*(Before)*

*(After)*

**List of part numbers affected**

687650005
687650050
687650073
687650074
687650098
687650099
687650101
687650102
687650107
687650116
687650119
687650136
687650138
687650154
687650154
687650163
687650164
687650165
687650166
687650167
687650168
687670069
687670120
687670124
687730006
687730030
687850018

Other attachments *(if OBS with replacement / SPQ changes)*


687850027
687880013
687880014
687880062
687880072
687880079
687880117
687880150
687880154
687880156
687880161