



# Product Change Notice

PCN Number: 12-1106-01  
Issue Date: July 2, 2013

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

## PRODUCTS AFFECTED:

SP483ECP-L	SP483EEP-L	SP485CS-L	SP485ECP-L	SP485EEP-L
SP485ES-L	SP485RCP-L	SP485REP-L	SP490ECP-L	SP490EEP-L
SP690ACP-L	SP690AEP-L	SP813LCP-L	SP813LEP-L	XR2209CP-F
XR4151CP-F	XRD5408AIP-F	XRD5410AIP-F	XRD5412AIP-F	XRD54L08AIP-F
XRD54L10AIP-F	XRD54L12AIP-F	XRT5675CP-F		

## CHANGE CATEGORY:

- Material  Process  Package  
 Design  Datasheet  Packing/Shipping  
 Other (Alternate Assembly Site)

**DESCRIPTION OF CHANGE:** Qualification of an alternate qualified PDIP assembly site, Cirtek (Philippines), in addition to the current assembly site, Unisem (Malaysia).

## IMPACT OF CHANGE:

There will be no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** October 2, 2013

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

### PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.