

PRODUCT CHANGE NOTIFICATION

PCN#: RACKS CABLE MGMT

20190815-1

ISSUE DATE: 20190904

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

The outer dimensions of the Patchlink Horizontal Manager cartons are changing. Full implementation of new cartons is expected to occur by October 23, 2019. Customers may receive mixed inventory until old carton inventory is depleted.

Part Number	Outside Dimensions											
	Old Dimensions						New Dimensions					
	Length		Width		Depth		Length		Width		Depth	
	In.	mm	In.	mm	In.	mm	In.	mm	In.	mm	In.	mm
WMPH2E	10.9	276.86	4.1	104.14	20.7	525.78	9.32	236.728	4.07	103.378	20.085	510.159
WMP1E	10.9	276.86	4.1	104.14	20.7	525.78	9.32	236.728	4.07	103.378	20.085	510.159
WMPFSE	4.295	109.093	2.21	56.134	21.397	543.4838	4.32	109.728	2.32	58.928	19.96	506.984
WMPLFSE	4.295	109.093	2.21	56.134	21.397	543.4838	4.32	109.728	2.32	58.928	19.96	506.984
WMPSE	10.4	264.16	2.6	66.04	20.9	530.86	9.445	239.903	2.445	62.103	20.085	510.159
WMPLSE	10.4	264.16	2.6	66.04	20.9	530.86	9.445	239.903	2.445	62.103	20.085	510.159

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2019	8	23
Old product discontinuation date*			

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)
WMPH2E
WMP1E
WMPFSE
WMPLFSE
WMPSE
WMPLSE