



4/28/2022

**Subject: Change Notification**

To our valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change in:

Type (Only Checked Changes Apply)		
<input checked="" type="checkbox"/> Production/assembly location	<input type="checkbox"/> Material	<input type="checkbox"/> End of Life w/ replacement
<input type="checkbox"/> Part Number/Ordering Code	<input type="checkbox"/> Packaging	<input type="checkbox"/> End of Life w/o replacement
<input checked="" type="checkbox"/> Country of Origin	<input type="checkbox"/> Point of Purchase	<input type="checkbox"/> Additional tool/refurbishment
<input type="checkbox"/> Design (fit, form, function)	<input type="checkbox"/> Point of Pick up	<input type="checkbox"/> Cost/Lead Time
<input type="checkbox"/> Engineering record (non-fit, form, function)	<input type="checkbox"/> Supply Chain	<input type="checkbox"/> Process

Additional Information	
<b>From:</b>	<b>To:</b>
HT Order Code:	HT Order Code:
111-12301	111-12301
DSWS50HSK2	DSWS50HSK2
157-00222	157-00222
157-00216	157-00216
157-00225	157-00225
157-00165	157-00165
151-01371	151-01371
157-00171	157-00171
S2CM258HIRHSH1	S2CM258HIRHSH1
151-01022	151-01022
157-00221	157-00221
157-00034	157-00034
SNP110C2	SNP110C2
157-00164	157-00164
151-01166	151-01166
SNP16GHS0M4	SNP16GHS0M4
157-00195	157-00195
133-04068	133-04068
FC2.2AH4	FC2.2AH4
157-00144	157-00144
157-00112	157-00112
151-01017	151-01017
SNP2810C2	SNP2810C2
MSMP6/109C2	MSMP6/109C2

SNP1GHS0C2	SNP1GHS0C2
156-01092	156-01092
SNP210C2	SNP210C2
SNP18A10C2	SNP18A10C2
111-12300	111-12300
SNP6010C2	SNP6010C2
126-00116	126-00116
RT50LL9C2	RT50LL9C2
SNP1010C2	SNP1010C2
SNP2410C2	SNP2410C2
SNP3210K2	SNP3210K2
SNP28GHS0H4	SNP28GHS0H4
SNP1.510C2	SNP1.510C2
SNP310M4	SNP310M4
IMP2.510C2	IMP2.510C2
SNP1.510M4	SNP1.510M4
SNP610C2	SNP610C2
SNP50GHS0C2	SNP50GHS0C2
SNP2210C2	SNP2210C2
157-00205	157-00205
SNP810C2	SNP810C2
SNP18A10M4	SNP18A10M4
Production Location: Milwaukee, WI	Production Location: Monterrey, MX
Country of Origin: Milwaukee, WI	Country of Origin: Monterrey, MX

**Scope**

<b>HT PN / Ordering Code</b>	<b>Customer PN</b>	<b>Change Effective*</b>
111-12301	<b>1436-1418-ND</b>	10/31/2022
DSWS50HSK2	<b>1436-1819-ND, DSWS50HSK2-ND</b>	
157-00222	<b>1436-1976-ND</b>	
157-00216	<b>1436-1974-ND</b>	
157-00225	<b>1436-2394-ND</b>	
157-00165	<b>1436-2378-ND</b>	
151-01371	<b>1436-151-01371-ND</b>	
157-00171	<b>1436-2382-ND</b>	
S2CM258HIRHSH1	<b>S2CM258HIRHSH1-ND</b>	
151-01022	<b>1436-1962-ND</b>	
157-00221	<b>1436-2392-ND</b>	
157-00034	<b>1436-1419-ND</b>	
SNP110C2	<b>1436-1323-ND</b>	
157-00164	<b>1436-2377-ND</b>	
151-01166	<b>1436-2440-ND</b>	
SNP16GHS0M4	<b>1436-1172-ND</b>	
157-00195	<b>1436-1973-ND</b>	
133-04068	<b>1436-133-04068-ND</b>	
FC2.2AH4	<b>1436-1084-ND</b>	

157-00144 | 1436-157-000144-ND  
157-00112 | 1436-2361-ND  
151-01017 | 1436-1961-ND  
SNP2810C2 | 1436-1369-ND  
MSMP6/109C2  
SNP1GHS0C2 | 1436-1327-ND  
156-01092 | 1436-2472-ND  
SNP210C2 | 1436-1326-ND  
SNP18A10C2 | 1436-1359-ND  
111-12300 | 1436-1417-ND  
SNP6010C2 | 1436-1400-ND  
126-00116 | 1436-2418-ND  
RT50LL9C2 | 1436-1628-ND  
SNP1010C2 | 1436-1344-ND  
SNP2410C2 | 1436-1364-ND  
SNP3210K2 | 1436-1299-ND  
SNP28GHS0H4 | 1436-1071-ND  
SNP1.510C2 | 1436-1325-ND  
SNP310M4 | 1436-1138-ND  
IMP2.510C2 | IMP2.510C2-ND  
SNP1.510M4 | 1436-1127-ND  
SNP610C2 | 1436-1333-ND  
SNP50GHS0C2 | SNP50GHS0C2-ND  
SNP2210C2 | 1436-1362-ND  
157-00205 | 1436-2387-ND  
SNP810C2 | 1436-1314-ND

\*Effective date is subject to change based on availability

We ask that you please acknowledge this notification by 7/19/2022, informing us if a new PPAP is required. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change.

Thank you for your business,

Dylan Goetzke  
Quality Project Administrator  
Office: 414 355 1130 x 8751  
Email: [dylan.goetzke@htamericas.com](mailto:dylan.goetzke@htamericas.com)