

PCN Number:	20180618000	PCN Date:	June 19, 2018
Title:	Datasheet for TPS1H100-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
		<input type="checkbox"/>	Wafer Bump Site
		<input type="checkbox"/>	Wafer Bump Material
		<input type="checkbox"/>	Wafer Bump Process
		<input type="checkbox"/>	Wafer Fab Site
		<input type="checkbox"/>	Wafer Fab Materials
		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



TPS1H100-Q1

SLVSCM2C – OCTOBER 2014 – REVISED JUNE 2018

Changes from Revision B (June 2015) to Revision C

Page

- Changed the *Pin Functions* table to alphabetical order and created separate columns for the Version A and Version B devices **3**
- Added tablenotes to the *Electrical Characteristics* table **7**
- Added the *Receiving Notification of Documentation Updates* section **39**

The datasheet number will be changing.

Device Family	Change From:	Change To:
TPS1H100-Q1	SLVSCM2B	SLVSCM2C

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TPS1H100-Q1>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

TPS1H100AQPWPRQ1	TPS1H100BQPWPRQ1		
------------------	------------------	--	--

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com