

PRODUCT OBSOLESCENCE NOTICE

**1 September 2010**

Dear Customer,

Murata Power Solutions (MPS) hereby gives official notification that the following product(s) you may have purchased from us are now obsolete. Unfortunately, we are not offering a Last-Time-Buy (LTB) due to the obsolescence of a major component that was used in this DC/DC converter.

Product Part Number	Recommended Alternative
HL02R05D12YC	No Recommendation
HL02R05D15YC	No Recommendation
HL02R05D15ZC/R	No Recommendation
HL02R05S05YC	NDY0505C
HL02R05S05ZC	No Recommendation
HL02R05S12YC	NDY0512C
HL02R05S12ZC	No Recommendation
HL02R12D12YC	No Recommendation
HL02R12D15YC	No Recommendation
HL02R15S05YC	NDY1205C
HL02R24D15YC	No Recommendation
HL02R24D15ZC	No Recommendation
HL02R24S05YC	NDY2405C
HL02R24S12YC	NDY2412C

Should you have any questions or concerns please contact your local MPS Representative, Distributor, or Regional Sales Manager at <http://www.murata-ps.com/offices.html>.