INFORMATION NOTE



N° 125/19

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Introduction of a data matrix code (DMC) marking affecting dedicated devices

Infineon Technologies AG Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0 Chairman of the Supervisory Board: Dr. Wolfgang Eder Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider Registered Office: Neubiberg Commercial Register: München HRB 126492

INFORMATION NOTE



N° 125/19

Introduction of a data matrix code (DMC) marking affecting dedicated devices

Products affected:	Please refer to attached affected product list 1_cip12519				
Detailed Change Information	rmation:				
Subject:	Introduction of a data matrix code (DMC) marking affecting dedicated devices				
Reason:	The data matrix code increases the internal traceability inside one lot				
Description:	<u>Old</u>	New			
Product marking:	Without DMC code on the backside of package:	 Without DMC code on the backside of package: 			
		or			
		L DYBER			
Data sheet update(s):	 Revision 1.0 	 Revision 1.1 (affecting products: TLE4946-2L, TLI4906L, TLI4946-2L) 			
	 Revision 1.1 	 Revision 1.2 (affecting products: TLV4906L, TLV4946-2L) 			

restricted

INFORMATION NOTE



N° 125/19

	 Revision 1.2 	 Revision 1.3 (affecting product: TLE4946-1L) 	
	 Revision 2.0 	 Revision 2.1 (affecting products: TLE4906L, TLE4966L, TLE4966L E6004) 	
Product Identification:	 Traceability is ensured by lot number visual appearance on package 		
Impact of Change:	DMC is already printed on similar products without any impact known. Only visual change on package backside but no further change on fit, form and function.		
Attachments:	Affected product list 1_cip12519		
Intended start of delivery:	From January 2021 onwards		

If you have any questions, please do not hesitate to contact your local Sales office.



Sales name	SP number	OPN	Package
TLE4906L	SP000012949	TLE4906LHALA1	PG-SSO-3-2
TLE4946-1L	SP000015003	TLE49461LHALA1	PG-SSO-3-2
TLE4946-2L	SP000398352	TLE49462LHALA1	PG-SSO-3-2
TLE4966L	SP000014135	TLE4966LHALA1	PG-SSO-4-1
TLE4966L E6004	SP000419394	TLE4966LE6004HBXA1	PG-SSO-4-1
TLI4906L	SP000604320	TLI4906LHALA1	PG-SSO-3-2
TLI4946-2L	SP000604336	TLI49462LHALA1	PG-SSO-3-2
TLV4906L	SP000604324	TLV4906LHALA1	PG-SSO-3-2
TLV4946-2L	SP000604340	TLV49462LHALA1	PG-SSO-3-2