

IloT Product Change Notice

The change will be applied on the BB-CANOP. If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.


- Reason for the Change:** Parts shortage.
- Affected Products:** BB-CANOP.
- Impact on Application:**

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	No
Physical Outlook Change	Yes
Ordering P/N Change	No
Cut-in Implement	Component Running Change

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
BB-CANOP	Weidmuller 1557410000	Weidmuller 1948800000	Terminal Block	Color Change	Parts availability
BB-CANOP	Weidmuller 1557310000	Weidmuller 1948240000	Terminal Block	Color Change	Parts availability

The preferred black terminal block is currently not available and we are substituting an orange version that has the same electrical specifications. This is necessary due to a world-wide shortage of plastics and resins. This change does not affect any certification. Until the parts situation is resolved, the color of the terminal block may be black or orange. Colors should not be mixed on the same product.



5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
BB-CANOP	n/a	6/22/2021	Running Change	TB Color change

*Note: Cut-in progress depends on factory production schedule, listed in this table is ESTIMATED time-frame.

Contact Windows

PM	Brian Foster / brian.foster@advantehc.com
AE	Chris Politsch / Chris.Politsch@advantech.com