

Light is OSRAM

01.12.2016

## OS-PD-2016-042

<b>Last order:</b>	01.03.2017
<b>Last delivery:</b>	01.09.2017
<b>Reason:</b>	Dimmer brightness not feasible to support

Please direct your inquiry to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Brand	Device	Ordering Code	Function	Brand
<b>DURIS S2</b>							
GW SBLMA2.EM-GUHP-XX35-L1M1-65-R18-XX	Q65111A8481	LED	DURIS S2	GW SBLMA2.EM-HQHS-XX35-1-65-R18	Q65111A9297	LED	DURIS S2
GW SBLMA2.EM-GUHP-XX37-L1M1-65-R18-XX	Q65111A8480	LED	DURIS S2	GW SBLMA2.EM-HPHR-XX37-1-65-R18	Q65111A9299	LED	DURIS S2
GW SBLMA2.EM-HPHQ-XX31-L1M1-65-R18-XX	Q65111A9893	LED	DURIS S2	GW SBLMA2.EM-HPHR-XX31-1-65-R18	Q65111A9304	LED	DURIS S2

## *Products Affected by Product Discontinuation Notification*

**Number:** OS-PD-2016-042

**Name:** Discontinued due to dimmer brightness no longer feasible

**Release Date:** 12/1/2016

**Last Order:** 3/1/2017

**Last Delivery:** 9/1/2017

### *DISCONTINUED*

### *NEW (REPLACEMENT)*

<i>Product</i>	<i>QNumber</i>	<i>QNumber Description</i>	<i>Part Number</i>	<i>Product</i>	<i>QNumber</i>	<i>QNumber Description</i>	<i>Part Number</i>
GW SBLMA2	Q65111A8480	GW SBLMA2.EM-GUHP-XX37-L1M1-65-R18-	GW SBLMA2.EM-GUHP-XX37-L1M1-	GW SBLMA2	Q65111A9299	GW SBLMA2.EM-HPHR-XX37-1-65-R18	GW SBLMA2.EM-HPHR-XX37-1
GW SBLMA2	Q65111A8481	GW SBLMA2.EM-GUHP-XX35-L1M1-65-R18-	GW SBLMA2.EM-GUHP-XX35-L1M1-	GW SBLMA2	Q65111A9297	GW SBLMA2.EM-HQHS-XX35-1-65-R18	GW SBLMA2.EM-HQHS-XX35-1
GW SBLMA2	Q65111A9893	GW SBLMA2.EM-HPHQ-XX31-L1M1-65-R18-	GW SBLMA2.EM-HPHQ-XX31-L1M1-	GW SBLMA2	Q65111A9304	GW SBLMA2.EM-HPHR-XX31-1-65-R18	GW SBLMA2.EM-HPHR-XX31-1