



Product Change Notification

PCN No: DAS-18-0430-CCB-1022

Qualification of carrier tape replacement GP01-D232-163A

Notification Date: 07/19/2018

Qualification Data Availability Date: See Attached Validation File

Notification Period: 30 days

Sample Availability Date: 07/19/2018

Proposed First Ship Date for Change: 08/18/2018

Last Date of Manufacture of Unchanged Product: 12/24/2018

Dear Valued Skyworks Customer:

Please be advised that Skyworks Solutions Inc. is introducing the following product change(s):

Description and Scope of Change

Addressing customer complaints regarding adhesive residues on SMT Jigs triggering jamming and causing the units to be thrown from carrier tape pockets. In order to avoid this situation, HSA sealing tape is proposed; Heat activated tape left no glue residues on SMT line.

Products Affected

3663IWO-4.2-2; SKY13314-374LF; SKY13314-374LFP; SKY13317-373LF; SKY13319-374LF; SKY13320-374LF; SKY13348-374LF; SKY13355-374LF; SKY13370-374LF; SKY13370-374LFP; SKY13381-374LF; SKY13411-374LF; SKY13421-486LF; SKY13431-374LF; SKY13438-374LF; SKY13446-374LF; SKY13523-639LF; SKY13524-639LF; SKY13575-639LF; SKY13591-373LF; SKY13593-690LF; SKY65404-21; SKY65404-31; SKY65405-21; SKY65513-11; SKY90006-374LFT; SKY90007-374LF; SKYA21027

Method for Identifying Changed Product

Full product change traceability is maintained by: date code

Reason for Change

Addressing customer complaints regarding adhesive residues on SMT Jigs triggering jamming and causing the units to be thrown from carrier tape pockets.

Anticipated Impact on Form, Fit Function, Reliability, Quality or Safety

There is no change to form, fit, function, reliability, quality or safety of the product. Carrier tape will be less prone to jamming at the customer site.

Qualification Plan Summary

Please see validation presentation.

Launch Plan

Consume existing inventory of Carrier tape -163A and replace with -657A

Please contact your Skyworks customer service representative with any questions or comments regarding this change. If you are unsure whom to contact, please email Skyworks Change Management at Skyworks.CCB@Skyworksinc.com.

Skyworks Solutions, Inc.

20 Sylvan Road, Woburn, MA 01801

USA: (781) 376-3000 • Asia: 886 2 2735 0399

Europe: 33 (0)1 43548540 • Fax: (781) 376-3300

On the Web: www.skyworksinc.com