

**CORPORATE HEADQUARTERS**

707 Dayton Road  
PO Box 1040  
Ottawa, IL 61350  
USA

p: 800-346-3119  
f: 815-433-5109

**EUROPEAN HEADQUARTERS**

Unit 10  
Westlink Commercial Park  
Oranmore, Co. Galway  
Ireland

p: + 353 91 792444  
f: + 353 91 792445

**CONEL S.R.O.**

Sokolská 71  
562 04 Ústí nad Orlicí III.  
Czech Republic

p: +420 465 521 020  
f: +420 464 647 299

**CALIFORNIA OFFICE**

Suite #210  
25531 Commercentre Dr.  
Lake Forest, CA 92630  
USA

p: 949-465-3000  
f: 949-465-3020

**EOL McPIM series**

3/15/2016

Part Number	Description
855-12840	McPIM, TP/FO-MM850-ST
855-12841	McPIM, TP/FO-MM850-SC
855-12842	McPIM, TP/FO-MM1300-ST
855-12843	McPIM, TP/FO-MM1300-SC
855-12844	McPIM, TP/FO-SM1310/PLUS-ST
855-12845	McPIM, TP/FO-SM1310/PLUS-SC
855-12846	McPIM, TP/FO-SM1310/LONG-ST
855-12847	McPIM, TP/FO-SM1310/LONG-ST
855-12848	McPIM, TP/FO-SM1550/LONG-ST
855-12849	McPIM, TP/FO-SM1550/LONG-ST

Advantech B+B SmartworX (IMC Networks) announces the last-time-buy and end-of-life for the products listed in the table; customers may place “last time buy” orders until September 1, 2016, or until available inventory is exhausted.

The 855-128XX series, the McPIM, a 10Mbps Module, is facing End of Life. A chip is no longer available, and due to low sales, the product will be phased out immediately.

**Product Migration Path:**

The iMcV-PIM, a 10Mbps Module, is a larger form factor, but still available to support 10Mbps Ethernet network connections.

**Recommended product replacement:**

The iMcV-PIM, 850-1494X. This module requires an iMediaChassis, MediaChassis or IE-MediaChassis series.

For details and product recommendations, please contact [techsupport@bb-smartworx.com](mailto:techsupport@bb-smartworx.com)

Thank You,



Susan Stanley, Product Training Manager, Network Infrastructure  
[ssstanley@advantech-bb.com](mailto:sstanley@advantech-bb.com)