

PCN: V19-001- SD474520-0A

Product Change Notice

Issue Date: 30th August 2019

Change Type:

Standard Packaging Incremental (SPI) quantity change.

Parts Affected:

The products affected by the change are:

ASMB-LTB2-0A333
ASMB-LTC2-0A335
ASMB-LTD2-0A333
Q1MB-LTD2-0A333
QSMB-LTB2-0A333
ASMB-LTB3-0C3F3
ASMB-LTC3-0D335
ASMB-LTD3-0C3F3

Description and Extent of Change:

For part numbers listed above, the Standard Packaging Incremental (SPI) will be changed from 4000pcs to 3500pcs per reel.

Reasons for Change:

Product packaging improvement.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change on form, fit and function of the product. Corresponding label change to reflect new SPI quantity

Existing	New
 N1238101011 ITEM DESC: LS0058 (1P)Item: ASMB-LTB2-0A333 DC: 1908 Lot: 1908201238101011A Fab/Bump: COO: CN Wafer Lot: (Q)QTY: 4000 Seal Date: 18-Feb-2019 RoHS Compliant Halogen Free e4 Max Temp 260 C MSL 5a (P)Customer Item: Dept ID: CMTLED CAT: T2V2R2 BIN: CA VF:	 N1238101012 ITEM DESC: LS0058 (1P)Item: ASMB-LTB2-0A333 DC: 1908 Lot: 1908201238101012A Fab/Bump: COO: CN Wafer Lot: (Q)QTY: 3500 Seal Date: 18-Feb-2019 RoHS Compliant Halogen Free e4 Max Temp 260 C MSL 5a (P)Customer Item: Dept ID: CMTLED CAT: T2V2R2 BIN: CA VF:



Effective Date of Change:

The shipment with above change will commence 90days after issuance date above.

Qualification Data:

Not applicable

These changes have been reviewed and approved by Broadcom engineers and managers per Broadcom procedure: Change Control and Customer Notification, A-5962-6052-80.

Please contact your Broadcom field sales engineer or Contact Center (<http://www.broadcom.com>) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days