

End of Life Notification

Date: January 5, 2011
EOL Reference: EOL 190
Product Reference: MER lead-bearing

Dear Customer,

As always we appreciate your use of International Rectifier semiconductor products. Our commitment to customer satisfaction and continuous improvement is demonstrated by our change plans to enhance capacity, quality and reliability. This notice is to inform you that the following products will be discontinued.

Type of Change Notification:

End of life for MER lead-bearing parts

Reason For End-Of-Life:

Product Portfolio Rationalization (Lead-bearing to Lead-Free)

Products Affected:

PartNo	PartNo	PartNo	PartNo
75-0037N	PVAZ172N	PVI5013R	PVT312S
75-0039	PVD1352N	PVI5013RS-T	PVT322AS
75-0058	PVD1352NS	PVI5033R	PVT322AS-T
PVA1352N	PVD1354N	PVI5033RS	PVT322S
PVA1352NS	PVD1354NS	PVI5050NS	PVT412
PVA1354N	PVDZ172N	PVI5080N	PVT412LS
PVA1354NS	PVG612	PVN012	PVT412S
PVA2352N	PVG612AS	PVN012S	PVT422
PVA2352NS	PVG612AS-T	PVN012S-T	PVT422S
PVA3054N	PVG612S	PVR1300N	PVT422S-T
PVA3054NS	PVG612S-T	PVR3301N	PVU414
PVA3055N	PVI1050N	PVT312	PVU414S
PVA3055NS	PVI1050NS	PVT312L	PVU414S-T
PVA3354N	PVI1050NS-T	PVT312LS	PVX6012

Effective Dates:

Customer Notice:	January 5, 2011
Last Time Buy:	July 5, 2011
Last Schedule Shipment:	January 5, 2012
Final Return Date:	April 5, 2011
Expiration of Ship & Debit:	April 5, 2011

Replacement Parts:

75-0037N	75-0037NPBF
75-0039	None
75-0058	75-0058PBF
PVA1352N	PVA1352NPBF
PVA1352NS	PVA1352NSPBF
PVA1354N	PVA1354NPBF
PVA1354NS	PVA1354NSPBF
PVA2352N	PVA2352NPBF
PVA2352NS	PVA2352NSPBF
PVA3054N	PVA3054NPBF
PVA3054NS	PVA3054NSPBF
PVA3055N	PVA3055NPBF
PVA3055NS	PVA3055NSPBF
PVA3354N	PVA3354NPBF
PVAZ172N	PVAZ172NPBF
PVD1352N	PVD1352NPBF
PVD1352NS	PVD1352NSPBF
PVD1354N	PVD1354NPBF
PVD1354NS	PVD1354NSPBF
PVDZ172N	PVDZ172NPBF
PVG612	PVG612PBF
PVG612AS	PVG612ASPBF
PVG612AS-T	PVG612AS-TPBF
PVG612S	PVG612SPBF
PVG612S-T	PVG612S-TPBF
PVI1050N	PVI1050NPBF
PVI1050NS	PVI1050NSPBF
PVI1050NS-T	PVI1050NS-TPBF
PVI5013R	PVI5013RPBF
PVI5013RS-T	PVI5013RS-TPBF

International Rectifier

101 Sepulveda Blvd., El Segundo, CA 90245 USA

Telephone: +1 310 726 8000

www.irf.com

PVI5033R	PVI5033RPBF
PVI5033RS	PVI5033RSPBF
PVI5050NS	PVI5050NSPBF
PVI5080N	PVI5080NPBF
PVN012	PVN012PBF
PVN012S	PVN012SPBF
PVN012S-T	PVN012S-TPBF
PVR1300N	PVR1300NPBF
PVR3301N	PVR3301NPBF
PVT312	PVT312PBF
PVT312L	PVT312LPBF
PVT312LS	PVT312LSPBF
PVT312S	PVT312SPBF
PVT322AS	PVT322ASPBF
PVT322AS-T	PVT322AS-TPBF
PVT322S	PVT322SPBF
PVT412	PVT412PBF
PVT412LS	PVT412LSPBF
PVT412S	PVT412SPBF
PVT422	PVT422PBF
PVT422S	PVT422SPBF
PVT422S-T	PVT422S-TPBF
PVU414	PVU414PBF
PVU414S	PVU414SPBF
PVU414S-T	PVU414S-TPBF
PVX6012	PVX6012PBF

Contact Information:

CONTACT TYPE	NAME	PHONE	EMAIL
PCN Coordinator	John Michaelson	951 375-4432	Jmichae2@irf.com