

PRODUCT CHANGE NOTIFICATION

Product Category SURFACE RACEWAY 20211110-1

Product Group ROAR

ISSUE DATE: 10-Nov-21

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Some surface raceway products will be discontinued with replacement parts.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2021	11	29
Old product discontinuation date*	2022	2	8

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
AFR4BCIW6	Compatible	AFR4BCBL6
AFR4CCIW	Compatible	AFR4CCBL
AFR4ECIW	Compatible	AFR4ECBL
AFR4JB2SIW	Compatible	AFR4JB2SBL
AFR4RAIW	Compatible	AFR4RABL
AFR4TRT70IW	Compatible	AFR4TRT70BL
AFR4WTRIW	Compatible	AFR4WTRBL
AFR4TBLGIW	Compatible	AFR4TBLGBL