

**PCN: V19-013-476103-OA**

## **Product Change Notice**

**Issue Date: 1st Nov'19**

**Change Type: Set screw with Loctite Coating for HEDR-5420-ES214 encoder.**

### **Parts Affected:**

<b>Part Number</b>	<b>Product Description</b>
HEDR-5420-ES214	Mini En,Set Scr,200CPR,Ears,5mm

### **Description and Extent of Change:**

Implementation of set screw with Loctite coating to secure in the hub thread of the reflective encoder HEDR-5420-ES214. The Loctite coating at the set screw validated and able to withhold set screw within hub thread.

Please refer to the set screw with Loctite coating shared below:

**Photo#1- Current set screw**



**Photo#2- Set screw with Loctite coating**



### **Reasons for Change:**

This is a counter measure for the issue highlighted by customer on missing or drop off set screw. This solution tends to up-hold the setscrew within the hub thread for easy installation and application.



**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

There is no form, fit, function or product reliability change.

**Effective Date of Change:** By 1<sup>st</sup> week of Nov' 2019

---

These changes have been reviewed and approved by Broadcom engineers and managers per Broadcom procedure: Change Control and Customer Notification.

Please contact your Broadcom field sales engineer or Contact Center (<http://www.broadcom.com/contact/>) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.