

<b>Product Name:</b>	HPL-599 - MICROSPACE	
	Microspace header horizontal	
<b>Product Manager:</b>	Dorian MOYNE	
<b>Subject:</b>	Notification of Planned Change	
<b>Distribution:</b>	Affected customers	
<b>Type of Change:</b>	Packaging Change	
<b>Change Description:</b>	We will change the shape of the tape cavity, by increasing the contact surface of the header in the bottom of the cavity.	
<b>Reason for Change:</b>	This change stands to improve the stability of the product in the tape, to have a better positioning for pick & placement technology at customer place.	
<b>Affected Parts:</b>	See Affected parts.xls file	
<b>Effective Date of Change:</b>	January,07 2023	<i>Note PCN22121R1 is revision to previous release version dtd Nov 08, 2022. Revision is to change affected partnumbers and correct the effective date as January 07,2023 instead of January 07 2022</i>
<b>Last Time Buy Date:</b>		
<b>Earliest Disty Return Date:</b>		
<b>Last Time Shipment Date</b>		
<b>Datasheet Attached?</b>	Yes	
<b>Qual/Test Data Attached?</b>	Yes	
<b>Samples Availability Date:</b>	07 January ,2023	
<b>Available Alternatives?</b>		
<b>Questions?</b>	<i>Contact your local ACS Representative, or Product Manager</i>	
	<i>Dorian MOYNE / Product Manager</i>	
	<i>dorian.moyne@amphenol-fci.com</i>	

**Note:**

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

**MPN**

10142344-105KLF

10142344-205KLF

10142344-305KLF

List of part numbers removed from PCN22121

10142344-205KVLF

10142344-305KVLF

10154415-105KVLF

10142344-105KVLF