

Product Discontinuation



PD_045_16

■ Last Order Date:	2016-12-30
■ Last Delivery Date:	2017-06-30

Reason: Last existing Non-HF compound MP 8000 CH4 at Inhouse TO252

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
SPD01N60C3	SP000307382	SPD01N60C3BTMA1	PG-TO252-3	none			
SPD02N60C3	SP000308771	SPD02N60C3BTMA1	PG-TO252-3	IPD60R3K3C6	SP001117718	IPD60R3K3C6ATMA1	PG-TO252-3
SPD02N60S5	SP000313943	SPD02N60S5BTMA1	PG-TO252-3	IPD60R3K3C6	SP001117718	IPD60R3K3C6ATMA1	PG-TO252-3
SPD03N60S5	SP000307393	SPD03N60S5BTMA1	PG-TO252-3	IPD60R1K4C6	SP001292870	IPD60R1K4C6ATMA1	PG-TO252-3
SPD04N60S5	SP000313946	SPD04N60S5BTMA1	PG-TO252-3	IPD60R950C6	SP001117730	IPD60R950C6ATMA1	PG-TO252-3

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!