



## Not Recommended for New Design: PAN1323 and PAN1327 Series

NRFND.PG13315.9.26.2016

September 26, 2016

**About this Notice:**

PAN1323, PAN13x7 Series, Bluetooth Module Not Recommended For New Design

**Effective Date:**

Immediate

**Change Details:**

The PAN1323, PAN1317 and PAN1327 Series RF modules are Not Recommended For New Designs. The replacement part numbers detailed in this document should be designed in to all NEW designs moving forward.

The PAN1316B and PAN1326B are 100% hardware and firmware compatible with the products they replace.

**Affected Parts:**

NRFND		Replacement	
Series	Part Number	Series	Part Number
PAN1317	ENW-89827C2JF	PAN1316B	ENW-89823C3KF
	ENW-89827C2KF		
PAN1323	ENW-89842A2JF	PAN1326B	ENW-89823A3KF
	ENW-89842A2KF		
PAN1327	ENW-89827A2JF	PAN1326B	ENW-89823A3KF
	ENW-89827A2KF		

**Datasheet(s):**

Attached

**Notes:**

Panasonic's policy and commitment to our customers as an RF Module manufacturer is to continue producing part numbers, or their direct replacements, for a long as there is demand in production volumes.