

PCN Number: RC131806A (Revised 06/20/14)
See Changes in Blue Text

Notification Date*: May 15, 2013

Title: AT91SAM9M11 Migration to Marketing Revision Level B							
Product Identification: Ordering code and topside marking							
<table border="1"> <tr> <th>EOL Ordering Code</th> <th>New Ordering Code</th> </tr> <tr> <td>AT91SAM9M11-CU*</td> <td>AT91SAM9M11B-CU</td> </tr> </table>		EOL Ordering Code	New Ordering Code	AT91SAM9M11-CU*	AT91SAM9M11B-CU		
EOL Ordering Code	New Ordering Code						
AT91SAM9M11-CU*	AT91SAM9M11B-CU						
*Lifetime extended to end of 2014							
Reason for Change:	<input type="checkbox"/> Material / Composition <input type="checkbox"/> Processing / Manufacturing	<input checked="" type="checkbox"/> Design / Firmware <input type="checkbox"/> Logistics	<input type="checkbox"/> Manufacturing Location <input type="checkbox"/> Quality / Reliability				
Change Description: A detailed description of the differences between the Marketing Revision Level (MRL) A and B can be found in the data sheet. In summary, changes are limited to the correction of the following errata:							
<ul style="list-style-type: none"> • USB High Speed Host : Packet loss in the UTMI transceiver (section 53.3.9.1 in datasheet) • USB High Speed Host and Device Port : USB does not startup after power-up (section 53.3.10.1 in datasheet) • Boot ROM: Boot issue on AT45-series SPI dataflash fixed (section 53.2.1.2) • UHPHS/UDPHS: Bad Lock of the USB High speed transceiver DLL (section 53.2.9.2). Issue fixed 							
To increase manufacturing flexibility and ensure a long-term continuity of supply, Atmel will manufacture the AT91SAM9M11B-CU using both gold (Au) and copper bond (Cu) wires. Atmel reserves the right to ship devices with either gold or copper bond wires. The change will not impact reliability, soldering profiles or electrical characteristics.							
Revised due to change: Boot on SDCard is not functional on MRL B							
<u>New Errata introduced and limited only to MRL B</u>							
49.3.1 Boot ROM (Limited to MRL B)							
49.3.1.1 Boot ROM: SDCARD Boot is not functional on MRL B							
The SDCard boot functionality does not work due to an issue in the ROM Code.							
Problem Fix/Workaround							
None							
Identification Method to Distinguish Change: Marketing Revision Level (MRL) has been incremented on top side marking to B .							
Qualification Data:	<input checked="" type="checkbox"/> Available	<input type="checkbox"/> Will be available (mm/dd/yr):	<input type="checkbox"/> Not Applicable				

ATMEL Rousset • Zone industrielle 13106 ROUSSET Cedex • France

Samples:	<input checked="" type="checkbox"/> Available	<input type="checkbox"/> Will be available (mm/dd/yr):	<input type="checkbox"/> Not Applicable
-----------------	---	--	---

Quantifiable Impact on Quality & Reliability:
None

Forecasted Availability Date: Now
Last Time Buy Date: December 31st 2014
Last Ship Date: March 31st 2015

**All orders placed after the notification date are non-cancellable and non-returnable (NCNR).*

Atmel Contact: Please contact your Atmel Sales Representative or Distributor for additional information (when replying via e-mail please include PCN number in subject line).

Information provided herein is in connection with Atmel products and this information is provided "AS IS". Atmel assumes no responsibility for any errors that may appear in this document. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Atmel's Terms and Conditions of Sale for such products, Atmel assumes no liability whatsoever, and Atmel disclaims any express or implied warranty, including liability or warranties relating to fitness for a particular purpose, merchantability, or non-infringement of any patent, copyright or other intellectual property right. Atmel products are not intended for use in a product or system intended to support or sustain life which, if it fails, can be reasonably expected to result in significant personal injury. Atmel may make changes to specifications and product descriptions at any time, without notice.

Attention Distributors: Product(s) identified in this notification will become obsolete and as such this EOL notification will act as the official written notification. All obsolete products will be listed in the next published quarterly distributor price book, following an PCN/EOL change, and listed on the obsolescence form which accompanies said price book. Within thirty (30) days from the published date of the price book, Distributor shall notify Atmel in writing of Distributor's then current inventory of the obsolete product

CUSTOMER ACKNOWLEDGEMENT OF RECEIPT: Atmel requests you acknowledge receipt of this PCN / EOL. Please complete and email to pcnadm@atmel.com and the Atmel Contact listed above. In your acknowledgement, you can grant approval or request additional information. **Atmel will deem this change accepted unless specific conditions of acceptance are provided in writing within 30 days from the date of this notice.**

Company: Name: Title: Date: Email Address: Location: Comments:	
---	--