

Light is OSRAM

30.07.2021

withdrawal of OS-PDN-2021-051

Dear valued customer,

the PDN Notification OS-PDN-2021-051 for our MIDLED product family was sent by accident to you as this product discontinuation is customer specific.

The MIDLED devices you're ordering are not affected and at this point we are not planning discontinuations.

We apologize for the mistake and any inconvenience caused.

Thank you for your business

OSRAM Opto Semiconductors GmbH

Head Office:

Leibnizstrasse 4

93055 Regensburg, Germany

Phone +49 941 850-5

Fax +49 941 850-1002

www.osram-os.com

Notification	Device	Product Descr.	Ordering Code	Brand	Reason	Repl. Product Descr.	Repl. Ordering Code
OS-PDN-2021-051	SFH 4655	SFH 4655-Z	Q65110A1569	MIDLED	material discontinuation	SFH 4350	Q65110A2091
OS-PDN-2021-051	SFH 4650	SFH 4650-Z	Q65110A1572	MIDLED	material discontinuation	SFH 4059S	Q65111A0278
OS-PDN-2021-051	SFH 3600	SFH 3600-Z	Q65110A1573	MIDLED	material discontinuation	SFH 3219	Q62702P5551
OS-PDN-2021-051	SFH 3605	SFH 3605-Z	Q65110A1574	MIDLED	material discontinuation	SFH 3015 FA	Q65110A9730
OS-PDN-2021-051	SFH 3605	SFH 3605-3/4-Z	Q65110A2664	MIDLED	material discontinuation	SFH 3015 FA	Q65110A9730
OS-PDN-2021-051	SFH 3600	SFH 3600-3/4-Z	Q65110A2666	MIDLED	material discontinuation	SFH 3219	Q62702P5551
OS-PDN-2021-051	SFH 4650	SFH 4650-UV-Z	Q65110A7888	MIDLED	material discontinuation	SFH 4059S	Q65111A0278
OS-PDN-2021-051	SFH 4641	SFH 4641-Z	Q65110A8098	MIDLED	material discontinuation	SFH 4544	Q65111A4886
OS-PDN-2021-051	SFH 4646	SFH 4646-Z	Q65110A8099	MIDLED	material discontinuation	SFH 4045N	Q65111A3903
OS-PDN-2021-051	SFH 4656	SFH 4656-Z	Q65110A8395	MIDLED	material discontinuation	SFH 4350	Q65110A2091
OS-PDN-2021-051	SFH 4651	SFH 4651-Z	Q65110A8396	MIDLED	material discontinuation	SFH 4059	Q65111A2991
OS-PDN-2021-051	SFH 4645	SFH 4645	Q65110A9367	MIDLED	material discontinuation	SFH 4045N	Q65111A3903
OS-PDN-2021-051	SFH 4640	SFH 4640	Q65110A9369	MIDLED	material discontinuation	SFH 4248	Q65110A3304
OS-PDN-2021-051	SFH 4645	SFH 4645-UV-Z	Q65110A9606	MIDLED	material discontinuation	SFH 4045N	Q65111A3903
OS-PDN-2021-051	SFH 4650	SFH 4650-UV R33-Z	Q65110A9784	MIDLED	material discontinuation	SFH 4059S	Q65111A0278
OS-PDN-2021-051	SFH 4646	SFH 4646-T2V	Q65111A0354	MIDLED	material discontinuation	SFH 4045N	Q65111A3903
OS-PDN-2021-051	SFH 4651	SFH 4651-U	Q65111A0425	MIDLED	material discontinuation	SFH 4059	Q65111A2991
OS-PDN-2021-051	SFH 4451	SFH 4451	Q65111A2583	MIDLED	material discontinuation	SFH 4258	Q65110A2976
OS-PDN-2021-051	SFH 4655	SFH 4655-UV	Q65111A3814	MIDLED	material discontinuation	SFH 4350	Q65110A2091
OS-PDN-2021-051	SFH 4640	SFH 4640-UV	Q65111A3977	MIDLED	material discontinuation	SFH 4248	Q65110A3304
OS-PDN-2021-051	SFH 4140	SFH 4140	Q65111A4190	MIDLED	material discontinuation	SFH 4045N	Q65111A3903
OS-PDN-2021-051	SFH 4451	SFH 4451-UV	Q65111A4223	MIDLED	material discontinuation	SFH 4258	Q65110A2976
OS-PDN-2021-051	SFH 4441	SFH 4441	Q65111A4266	MIDLED	material discontinuation	SFH 4248	Q65110A3304
OS-PDN-2021-051	SFH 4651	SFH 4651-UV	Q65111A4394	MIDLED	material discontinuation	SFH 4059	Q65111A2991
OS-PDN-2021-051	SFH 4646	SFH 4646 E9587	Q65111A4559	MIDLED	material discontinuation	SFH 4045N	Q65111A3903
OS-PDN-2021-051	SFH 4641	SFH 4641-UV	Q65111A4669	MIDLED	material discontinuation	SFH 4544	Q65111A4886
OS-PDN-2021-051	SFH 4645	SFH 4645-V	Q65111A5761	MIDLED	material discontinuation	SFH 4045N	Q65111A3903
OS-PDN-2021-051	SFH 4641	SFH 4641-T1V	Q65111A5899	MIDLED	material discontinuation	SFH 4544	Q65111A4886
OS-PDN-2021-051	SFH 4646	SFH 4646-TV	Q65111A6148	MIDLED	material discontinuation	SFH 4045N	Q65111A3903
OS-PDN-2021-051	SFH 4641	SFH 4641-U-XX	Q65111A6466	MIDLED	material discontinuation	SFH 4544	Q65111A4886
OS-PDN-2021-051	SFH 4451	SFH 4451-V	Q65111A6962	MIDLED	material discontinuation	SFH 4258	Q65110A2976
OS-PDN-2021-051	SFH 4140	SFH 4140-U-XX	Q65111A7460	MIDLED	material discontinuation	SFH 4045N	Q65111A3903
OS-PDN-2021-051	SFH 4646	SFH 4646-UV	Q65111A8253	MIDLED	material discontinuation	SFH 4045N	Q65111A3903
OS-PDN-2021-051	SFH 4441	SFH 4441-V-XX	Q65112A1832	MIDLED	material discontinuation	SFH 4248	Q65110A3304
OS-PDN-2021-051	SFH 4441	SFH 4441 E9613	Q65112A5158	MIDLED	material discontinuation	SFH 4248	Q65110A3304
OS-PDN-2021-051	SFH 4655	SFH 4655-VAW	Q65112A6723	MIDLED	material discontinuation	SFH 4350	Q65110A2091
OS-PDN-2021-051	SFH 4441 E9621	SFH 4441 E9621	Q65112A8137	MIDLED	material discontinuation	SFH 4248	Q65110A3304
OS-PDN-2021-051	SFH 4650	SFH 4650-VAW	Q65112A8148	MIDLED	material discontinuation	SFH 4059S	Q65111A0278
OS-PDN-2021-051	SFH 4640	SFH 4640-VAW	Q65112A9418	MIDLED	material discontinuation	SFH 4248	Q65110A3304
OS-PDN-2021-051	SFH 3600	SFH 3600-3-Z-XX	Q65113A0241	MIDLED	material discontinuation	SFH 3219	Q62702P5551
OS-PDN-2021-051	SFH 4640	SFH 4640-V	Q65113A2226	MIDLED	material discontinuation	SFH 4248	Q65110A3304